


ORIGINAL

Gordon & Rees LLP  
101 West Broadway  
Suite 1600  
San Diego, CA 92101

1 BRIAN M. LEDGER (SBN: 156942)  
KRISTIN REYNA (SBN: 211075)  
2 GORDON & REES LLP  
101 West Broadway, Suite 2000  
3 San Diego, CA. 92101  
Telephone: (619) 696-6700  
4 Fax: (619) 696-7124  
  
5 JAN GOLDSMITH (SBN: 70988)  
FREDERICK M. ORTLIEB (SBN: 131751)  
6 DAVID J. KARLIN (SBN: 156178)  
OFFICE OF THE CITY ATTORNEY  
7 1200 Third Avenue, Suite 1100  
San Diego, CA. 92101  
8 Telephone: (619) 533-5800  
Fax: (619) 533-5856  
  
9 Attorneys for CITY OF SAN DIEGO  
10



11 UNITED STATES DISTRICT COURT  
12 FOR THE SOUTHERN DISTRICT OF CALIFORNIA

13 CITY OF SAN DIEGO ) Case No. 09 CV 2275 W CAB  
14 vs. Plaintiff, ) COMPLAINT FOR ENVIRONMENTAL  
15 ) COST RECOVERY AND  
16 ) CONTRIBUTION, INJUNCTIVE  
17 ) RELIEF, DECLARATORY RELIEF,  
18 ) AND DAMAGES  
19 )  
20 ) Demand For Jury Trial  
21 )  
22 )  
23 )  
24 )  
25 )  
26 )  
27 )  
28 ) Defendants.

FAXED

Gordon & Rees LLP  
101 West Broadway  
Suite 1600  
San Diego, CA 92101

1 Plaintiff City of San Diego ("Plaintiff") complains and alleges as follows:

2 **PARTIES**

3 1. Plaintiff is, and at all times material to this complaint has been, a municipal  
4 corporation in the County of San Diego, State of California.

5 2. Plaintiff is informed and believes, and on that basis alleges, that defendant  
6 NATIONAL STEEL & SHIPBUILDING COMPANY ("NAASCO") is a corporation organized  
7 and existing under the laws of the State of Nevada and is authorized to do business and is doing  
8 business in the State of California. Upon information and belief, NAASCO is a successor in  
9 interest to defendants National Steel and Shipbuilding Corporation and National Iron Works.

10 3. Plaintiff is informed and believes that defendant NATIONAL STEEL &  
11 SHIPBUILDING CORPORATION is a former corporation that was organized and existed under  
12 the laws of the State of California and was authorized to do business and did business in the State  
13 of California.

14 4. Plaintiff is informed and believes that defendant NATIONAL IRON WORKS is a  
15 former corporation that was organized and existed under the laws of the State of California and  
16 was authorized to do business and did business in the State of California.

17 5. Plaintiff is informed and believes that defendant MARTINOLICH SHIP  
18 BUILDING COMPANY is former corporation that was organized and existed under the laws of  
19 the State of California and was authorized to do business and did business in the State of  
20 California.

21 6. Plaintiff is informed and believes, and on that basis alleges, that defendant  
22 SOUTHWEST MARINE, INC. is a corporation organized and existing under the laws of the  
23 State of California and was authorized to do business and did business in the State of California.

24 7. Plaintiff is informed and believes, and on that basis alleges, that defendant BAE  
25 SYSTEMS SAN DIEGO SHIP REPAIR, INC. is the successor to SOUTHWEST MARINE,  
26 INC. ("BAE SYSTEMS")<sup>1</sup>, and is a corporation organized and existing under the laws of the

27 1 The term "BAE SYSTEMS" will be used to refer to BAE SYSTEMS SAN DIEGO SHIP REPAIR, INC.  
28 and/or SOUTHWEST MARINE, INC.

1 State of California, doing business in California.

2       8. Plaintiff is informed and believes, and on that basis alleges, that defendant SAN  
3 DIEGO MARINE CONSTRUCTION COMPANY is a former corporation that was organized  
4 and existed under the laws of the State of California and was authorized to do business and did  
5 business in the State of California.

6       9. Plaintiff is informed and believes, and on that basis alleges, that defendant STAR  
7 AND CRESCENT BOAT COMPANY, A DIVISION OF SAN DIEGO MARINE  
8 CONSTRUCTION COMPANY<sup>2</sup> is a former corporation that was organized and existed under  
9 the laws of the State of California and was authorized to do business and did business in the State  
10 of California.

11      10. Plaintiff is informed and believes, and on that basis alleges, that defendant STAR  
12 AND CRESCENT BOAT COMPANY is a former corporation that was organized and existed  
13 under the laws of the State of California and was authorized to do business and did business in  
14 the State of California.

15      11. Plaintiff is informed and believes, and on that basis alleges, that defendant STAR  
16 AND CRESCENT INVESTMENT COMPANY is a former corporation that was organized and  
17 existed under the laws of the State of California and was authorized to do business and did  
18 business in the State of California.

19      12. Plaintiff is informed and believes, and on that basis alleges, that defendant STAR  
20 AND CRESCENT FERRY COMPANY is a former corporation that was organized and existed  
21 under the laws of the State of California and was authorized to do business and did business in  
22 the State of California.

23      13. Plaintiff is informed and believes, and on that basis alleges, that defendant  
24 CAMPBELL INDUSTRIES is a corporation organized and existing under the laws of the State  
25 of California, authorized to do business in the State of California and did business in the State of

26      <sup>2</sup> The term "SDMCC DEFENDANTS" will be used to refer to SAN DIEGO MARINE CONSTRUCTION  
27 COMPANY; STAR AND CRESCENT BOAT COMPANY, a division of SAN DIEGO MARINE  
CONSTRUCTION COMPANY; STAR AND CRESCENT BOAT COMPANY; STAR AND CRESCENT  
INVESTMENT COMPANY; and STAR AND CRESCENT FERRY COMPANY.  
28

1 California.

2       14. Plaintiff is informed and believes, and on that basis alleges, that defendant  
 3 MCCSD is a former corporation that organized and existed under the laws of the State of  
 4 California and was authorized to do business and did business in the State of California. On  
 5 information and belief, MCCSD was a wholly owned subsidiary of CAMPBELL INDUSTRIES  
 6 and changed its name to defendant SAN DIEGO MARINE CONSTRUCTION  
 7 CORPORATION.

8       15. Plaintiff is informed and believes, and on that basis alleges, that defendant SAN  
 9 DIEGO MARINE CONSTRUCTION CORPORATION is a former corporation that was  
 10 organized and existed under the laws of the State of California and formerly did business in the  
 11 State of California.<sup>3</sup>

12       16. Plaintiff is informed and believes, and on that basis alleges, that defendant SAN  
 13 DIEGO GAS & ELECTRIC is a corporation organized and existing under the laws of the State  
 14 of California and is authorized to do business and does business in the State of California.

15       17. Plaintiff is informed and believes, and on that basis alleges, that defendant  
 16 UNITED STATES NAVY ("NAVY") is a branch of the United States military organized and  
 17 existing under federal law, and authorized to do business and does business in the State of  
 18 California. Plaintiff has submitted or is in the process of submitting a claim against NAVY  
 19 under the Federal Tort Claims Act for the tort claims Plaintiff has against NAVY related to the  
 20 Shipyard Sediment Site. Should NAVY deny Plaintiff's administrative claim as to the tort  
 21 claims, Plaintiff will seek leave of court to amend this complaint to name NAVY as a defendant  
 22 to each of the tort claims herein.

23       18. Plaintiff is informed and believes, and on that basis alleges, that defendant SAN  
 24 DIEGO UNIFIED PORT DISTRICT ("PORT DISTRICT") is a special governmental entity,  
 25 created in 1962 by the San Diego Unified Port District Act and California Harbors and  
 26 Navigation Code in order to manage San Diego Harbor, and administer certain public lands

27       <sup>3</sup> The term "CAMPBELL DEFENDANTS" will be used to refer to CAMPBELL INDUSTRIES, MCCSD,  
 28 and/or SAN DIEGO MARINE CONSTRUCTION CORPORATION.

Gordon & Rees LLP  
 101 West Broadway  
 Suite 1600  
 San Diego, CA 92101

1 along the San Diego Bay and is authorized to do business and does business in the State of  
2 California. Government Code section 905(i) authorizes Plaintiff, a local public entity, to bring  
3 these claims against Defendant PORT DISTRICT, another local public entity, without any prior  
4 administrative claims procedure.

5       19. Plaintiff is ignorant of the true names or capacities of the defendants sued herein  
6 under the fictitious names DOES 1 through 100, inclusive, and therefore sues these defendants  
7 by such fictitious names. Plaintiff will amend this complaint to allege their true names and  
8 capacities when ascertained. Plaintiff is informed and believes and thereon alleges that each of  
9 said fictitiously named defendants are, through their negligence, intentional torts, and/or conduct  
10 giving rise to said liability, responsible or liable in some manner for the occurrences herein  
11 alleged, and that the damages alleged herein were the direct and legal result of said actions or  
12 omissions.

### **NATURE OF ACTION**

14       20. Plaintiff and Defendants NASSCO, BAE SYSTEMS, CAMPBELL  
15 INDUSTRIES, SDG&E, and NAVY have all been named as “Dischargers” or “Persons  
16 Responsible” for alleged environmental contamination at the property known as the “Shipyard  
17 Sediment Site” by the California Regional Water Quality Control Board, San Diego Region (“the  
18 Regional Board”), in Tentative Clean Up & Abatement Order No. R9-2005-0126 (the “Tentative  
19 Order”). A copy of the Tentative Order is attached to this Complaint as Exhibit “A” and is  
20 incorporated by reference herein.

21       21. The Shipyard Sediment Site is a portion of San Diego Bay along the eastern shore  
22 of the Bay in an area extending from approximately the Sampson Street Extension to the north  
23 and Chollas Creek to the south, and from the NASSCO shipyard facility and BAE SYSTEMS  
24 shipyard facility shoreline out to the San Diego main shipping channel to the west.

25        22. The Regional Board contends that Plaintiff and defendants are jointly and  
26 severally responsible for alleged property damage, including, but not limited to alleged damage  
27 to aquatic life, at and beyond leaseholds at the Shipyard Sediment Site once and/or currently  
28 occupied by Defendants and other entities. The Regional Board contends that such property

1 damage and injury was proximately caused by historical contamination of the Bay by the alleged  
 2 Dischargers and various other entities. Upon information and belief, based on the Tentative  
 3 Order and historical records, the alleged property damage and injury at issue began in the early  
 4 twentieth century and has continued to the present.

5       23. The Regional Board contends that environmental investigations conducted at a  
 6 Shipyard Sediment Site revealed the presence of elevated levels of pollutants in the San Diego  
 7 Bay bottom marine sediment. The Regional Board has concluded that the contaminated marine  
 8 sediment has caused conditions of contamination in the San Diego Bay that adversely affects  
 9 aquatic life, aquatic-dependent wildlife, human health, and San Diego Bay beneficial uses. The  
 10 following hazardous substances have been detected in the sediment at the Shipyards Sediment  
 11 Site: Arsenic, Cadmium, Copper, Lead, Mercury, Zinc, Tributyltin ("TBT"), High Molecular  
 12 Weight Polynuclear Aromatic Hydrocarbons ("HPAHs"), and Polychlorinated Biphenyls  
 13 ("PCBs")<sup>4</sup>.

#### JURISDICTION

14       24. This Court has jurisdiction over the subject matter of this action pursuant to the  
 15 Comprehensive Environmental Response, Compensation and Liability Act (CERCLA), 42  
 16 U.S.C. §§ 9613(b) and (f), and 42 U.S.C. § 9607; pursuant to the Oil Pollution Act, 33 U.S.C.  
 17 § 2709; pursuant to the Declaratory Judgment Act, 28 U.S.C. § 2201; and pursuant to 28 U.S.C.  
 18 § 1331.

19       25. This Court also has subject matter jurisdiction over Plaintiff's claims brought  
 20 under state law by virtue of the supplemental jurisdiction provided in 28 U.S.C. § 1337, and  
 21 under the doctrine of pendent jurisdiction set forth in *United Mine Workers v. Gibbs*, 383 U.S.  
 22 715 (1966). Plaintiff's claims under state law arise from the same nucleus of operative facts as  
 23 the claims under federal law.

#### VENUE

24       26. Pursuant to 42 U.S.C. § 9613(b), venue is proper in any district in which the

---

25  
 26       <sup>4</sup> The hazardous substances identified in this sentence will be referred to as the constituents of concern  
 27 ("COCs").  
 28

1 release or damages occurred. The releases of hazardous substances and damages occurred in San  
 2 Diego, California, which is in the Southern District of California.

3 **GENERAL ALLEGATIONS/ BACKGROUND**

4 **A. PLAINTIFF**

5 27. Plaintiff City of San Diego owns and operates a municipal storm water system  
 6 (MS4) through which it discharges urban runoff to San Diego Bay subject to the terms and  
 7 conditions of its National Pollution Discharge Elimination System ("NPDES") permit under  
 8 section 402 of the Clean Water Act.

9 28. From approximately 1914-1962, Plaintiff served as the designated public trustee,  
 10 via an Act of the Legislature of the State of California approved May 1, 1911, for the tidelands  
 11 property on which Defendants NASSCO and BAE SYSTEMS presently operate (the NAASCO  
 12 and BAE SYSTEMS leaseholds, respectively). From 1914-1962, Plaintiff did not conduct any  
 13 operations on the property at any time; Plaintiff did not discharge any hazardous substances from  
 14 these properties; nor did Plaintiff cause or permit any hazardous substances to be discharged  
 15 from these properties. The Regional Board did not find Plaintiff's past role of public trustee of  
 16 this property to be a basis for naming Plaintiff a "Discharger" or "Responsible Party" under its  
 17 Tentative Order.

18 **B. NASSCO**

19 29. Upon information and belief, from approximately 1945 to present, NASSCO  
 20 and/or its predecessors in interest have owned and operated a full service ship construction,  
 21 modification, repair, and maintenance facility located at 2798 Harbor Drive (28<sup>th</sup> Street and  
 22 Harbor Drive) in San Diego, California. Upon information and belief, NASSCO leases the land  
 23 on which its facility operates from the PORT DISTRICT, the designated public trustee of the  
 24 property since assuming that function from Plaintiff in 1962 ("the NAASCO Leasehold").

25 30. NASSCO's primary business has historically been ship repair, construction, and  
 26 maintenance for the NAVY and commercial customers. Current site features include offices,  
 27 shops, warehouses, concrete platens for steel fabrication, a floating dry dock, a graving dock,  
 28 two shipbuilding ways, and five piers, which provide 12 berthing spaces.

Gordon & Rees LLP  
 101 West Broadway  
 Suite 1600  
 San Diego, CA 92101

1           31. Upon information and belief, the primary industrial processes which NASSCO  
 2 has historically conducted include: surface preparation and paint removal; paint application; tank  
 3 cleaning; mechanical repair/maintenance/installation; structural repair/alteration/assembly;  
 4 integrity/hydrostatic testing; paint equipment cleaning; engine repair/maintenance/installation;  
 5 steel fabrication and machining; electrical repair/maintenance/installation; hydraulic  
 6 repair/maintenance/installation; tank emptying; fueling; shipfitting; carpentry; and  
 7 refurbishing/modernization/cleaning.

8           32. Upon information and belief, the primary materials used by NASSCO in its  
 9 operations have historically included 1) abrasive grit (sometimes consisting of slag from coal-  
 10 fired boilers and often containing iron, aluminum, silicon, calcium oxides, copper, zinc and  
 11 titanium; also sand, cast iron or steel shot is used; enormous amounts are needed to remove paint  
 12 and it is needed in both wet and dry blasting); 2) paint (containing copper, zinc, chromium, lead,  
 13 and hydrocarbons; anticorrosive paint often containing lead and zinc; antifouling paint often  
 14 containing copper and tributyltin); 3) miscellaneous, including oils, grease, fuels, weld,  
 15 detergents, cleaners, rust inhibitors, paint thinners, hydrocarbon and chlorinated solvents,  
 16 degreasers, acids, caustics, resins, adhesives/cement/sealants and chlorine.

17           33. Upon information and belief, the wastes commonly generated by NASSCO  
 18 historically in its operations have been abrasive blast waste (with the largest concern being spent  
 19 paint containing, among other substances, copper, tributyltin, lead, chromium and zinc); fresh  
 20 paint; bilge waste/oily wastewater; blast wastewater; oils; waste paints; construction repair  
 21 wastes and trash; and miscellaneous wastes consisting of lubricants, grease, fuels, sewage, boiler  
 22 blowdown, condensate, discard, acid wastes, caustic wastes, and aqueous wastes.

23           34. In 1972, the Regional Board initiated an investigation to determine the amount of  
 24 and kinds of pollutants that entered San Diego Bay from shipbuilding and repair facilities, and  
 25 the possible effects that pollution could have on beneficial uses of the Bay. All shipbuilding and  
 26 repair facilities were inspected. The report noted, *inter alia*, the following:

27           a. It was estimated by workers and managers at all San Diego Bay shipyards  
 28 that 5-10 percent of the sand blasted waste and other waste was either intentionally or

Gordon & Rees LLP  
 101 West Broadway  
 Suite 1600  
 San Diego, CA 92101

1 accidentally discharged into the Bay. The Regional Board estimated that this resulted in 335  
 2 tons of sand, 27 tons of copper oxide, 3 tons of lead oxide and 1 ton of zinc chromate being  
 3 discharged to the Bay from shipyard operations for 1971 alone;

4                 b.         The Regional Board collected bay sediment core samples from 11 sites in  
 5 the Bay in March 1972. The results of the sampling indicated that heavy metal concentrations  
 6 were higher near shipbuilding and repair facilities than other locations.

7                 35.        Based on the data available for the years 1987-1991, NASSCO generates an  
 8 average of 198 tons of abrasive blast waste alone per month.

9                 36.        Prior to the early 1990s, when a storm water first-flush capture system was  
 10 installed for portions of the facility, all surface water runoff from NASSCO's operations was  
 11 intentionally or accidentally discharged directly into San Diego Bay.

12                 37.        During numerous inspections starting in the late 1980s, the Regional Board would  
 13 observe abrasive blast wastes at NASSCO's facility deposited in areas where it would probably  
 14 be discharged to the Bay via stormwater runoff. Samples of abrasive blast waste and other  
 15 wastes were collected in the vicinity of storm drains or other areas susceptible to being  
 16 transported to the Bay. For example:

17                 a.         During inspections by the Regional Board in August 1989, the inspector  
 18 reported that "...the sandblast pit is a major problem. Sandblast waste is everywhere w/o runoff  
 19 controls.";

20                 b.         During an inspection on October 16, 1991, the Regional Board inspector  
 21 reported "a threatened discharge to the storm drains from blasting, painting and dust collection  
 22 activities in the yard."

23                 c.         During an inspection on February 27, 1992, the Regional Board inspector  
 24 noted spent abrasive blast waste on storm drain surfaces.

25                 38.        The Regional Board has previously issued Administrative Civil Liability Orders  
 26 against NASSCO for discharges to the Bay, including:

27                 a.         On May 22, 1989, the Regional Board issued Complaint No. 89-42 to  
 28 NASSCO for discharge of spent abrasive waste from a floating dry dock to San Diego Bay and

Gordon & Rees LLP  
 101 West Broadway  
 Suite 1600  
 San Diego, CA 92101

1 for operating its graving dock in a manner in violation of a past order. NASSCO waived a  
 2 hearing and accepted liability for discharge of contaminated cooling water from the hull and  
 3 freeboard abrasive blast operations to the Bay, failing to prevent water flows from coming in  
 4 contact with sand blast residue in the graving dock, and discharge of slurry blast to the Bay.

5 b. On January 30, 2001, the Regional Board issued Complaint No. 2001-24  
 6 to NASSCO for violations of storm water runoff requirements of its NPDES permit. NASSCO  
 7 sampled 21 discharge points and all failed the discharge requirements.

8 39. The Regional Board has alleged in Tentative Order R9-2005-0126 that NASSCO  
 9 has caused or permitted waste from its shipyard operations to be discharged into the Bay in  
 10 violation of waste discharge requirements, and discharged or deposited waste where it was  
 11 discharged into the Bay creating, or threatening to create, a condition of pollution or nuisance.  
 12 The Regional Board has alleged that NASSCO violated Water Code section 13304 and violated  
 13 its NPDES permit requirements under the Clean Water Act section 402.

14 40. Upon information and belief, NAASCO has discharged the COCs from its  
 15 leasehold and these discharges have resulted in the contamination of the sediment at the  
 16 Shipyards Sediment Site.

17 C. **NATIONAL STEEL & SHIPBUILDING CORPORATION**

18 41. Upon information and belief, from approximately 1950 to 1960, defendant  
 19 NATIONAL STEEL & SHIPBUILDING CORPORATION and/or its predecessors in interest  
 20 owned and operated a full service ship construction, modification, repair, and maintenance  
 21 facility located at 2798 Harbor Drive (28<sup>th</sup> Street and Harbor Drive) in San Diego, California.  
 22 NATIONAL STEEL & SHIPBUILDING CORPORATION leased the land on which its facility  
 23 operated from Plaintiff.

24 42. Upon information and belief, NATIONAL STEEL & SHIPBUILDING  
 25 CORPORATION's primary business was ship repair, construction, and maintenance for the  
 26 NAVY and commercial customers. Site features are believed to have included offices, shops,  
 27 warehouses, concrete platens for steel fabrication, a floating dry dock, a graving dock, two  
 28 shipbuilding ways, and piers providing numerous berthing spaces.

Gordon & Rees LLP  
 101 West Broadway  
 Suite 1600  
 San Diego, CA 92101

1       43. Upon information and belief, the primary industrial processes which NATIONAL  
 2 STEEL & SHIPBUILDING CORPORATION conducted included: surface preparation and paint  
 3 removal; paint application; tank cleaning; mechanical repair/maintenance/installation; structural  
 4 repair/alteration/assembly; integrity/hydrostatic testing; paint equipment cleaning; engine  
 5 repair/maintenance/installation; steel fabrication and machining; electrical  
 6 repair/maintenance/installation; hydraulic repair/maintenance/installation; tank emptying;  
 7 fueling; shipfitting; carpentry; and refurbishing/modernization/cleaning.

8       44. Upon information and belief, the primary materials used by NATIONAL STEEL  
 9 & SHIPBUILDING CORPORATION in its operations included 1) abrasive grit (sometimes  
 10 consisting of slag from coal-fired boilers and often containing iron, aluminum, silicon, calcium  
 11 oxides, copper, zinc and titanium; also sand, cast iron or steel shot is used; enormous amounts  
 12 are needed to remove paint and it is needed in both wet and dry blasting); 2) paint (containing  
 13 copper, zinc, chromium, lead, and hydrocarbons; anticorrosive paint often containing lead and  
 14 zinc; antifouling paint often containing copper and tributyltin); 3) miscellaneous, including oils,  
 15 grease, fuels, weld, detergents, cleaners, rust inhibitors, paint thinners, hydrocarbon and  
 16 chlorinated solvents, degreasers, acids, caustics, resins, adhesives/cement/sealants and chlorine.

17       45. Upon information and belief, the wastes commonly generated by NATIONAL  
 18 STEEL & SHIPBUILDING CORPORATION in its operations were abrasive blast waste (with  
 19 the largest concern being spent paint containing, among other substances, copper, tributyltin,  
 20 lead, chromium and zinc); fresh paint; bilge waste/oily wastewater; blast wastewater; oils; waste  
 21 paints; construction repair wastes and trash; and miscellaneous wastes consisting of lubricants,  
 22 grease, fuels, sewage, boiler blowdown, condensate, discard, acid wastes, caustic wastes, and  
 23 aqueous wastes.

24       46. Upon information and belief, NATIONAL STEEL & SHIPBUILDING  
 25 CORPORATION discharged the COCs from its leasehold and these discharges have resulted in  
 26 the contamination of the sediment at the Shipyards Sediment Site.

27 C. **NATIONAL IRON WORKS**

28       47. Upon information and belief, from approximately 1945 to 1960, defendant

Gordon & Rees LLP  
 101 West Broadway  
 Suite 1600  
 San Diego, CA 92101

1 NATIONAL IRON WORKS owned and operated a full service ship construction, modification,  
2 repair, and maintenance facility located at 2798 Harbor Drive (28<sup>th</sup> Street and Harbor Drive) in  
3 San Diego, California. NATIONAL IRON WORKS leased the land on which its facility  
4 operated from Plaintiff.

5       48. Upon information and belief, NATIONAL IRON WORKS's primary business  
6 was ship repair, construction, and maintenance for the NAVY and commercial customers. Site  
7 features are believed to have included offices, shops, warehouses, concrete platens for steel  
8 fabrication, a floating dry dock, a graving dock, two shipbuilding ways, and piers providing  
9 numerous berthing spaces.

10      49. Upon information and belief, the primary industrial processes which NATIONAL  
11 IRON WORKS conducted included: surface preparation and paint removal; paint application;  
12 tank cleaning; mechanical repair/maintenance/installation; structural repair/alteration/assembly;  
13 integrity/hydrostatic testing; paint equipment cleaning; engine repair/maintenance/installation;  
14 steel fabrication and machining; electrical repair/maintenance/installation; hydraulic  
15 repair/maintenance/installation; tank emptying; fueling; shipfitting; carpentry; and  
16 refurbishing/modernization/cleaning.

17      50. Upon information and belief, the primary materials used by NATIONAL IRON  
18 WORKS in its operations included 1) abrasive grit (sometimes consisting of slag from coal-fired  
19 boilers and often containing iron, aluminum, silicon, calcium oxides, copper, zinc and titanium;  
20 also sand, cast iron or steel shot is used; enormous amounts are needed to remove paint and it is  
21 needed in both wet and dry blasting); 2) paint (containing copper, zinc, chromium, lead, and  
22 hydrocarbons; anticorrosive paint often containing lead and zinc; antifouling paint often  
23 containing copper and tributyltin); 3) miscellaneous, including oils, grease, fuels, weld,  
24 detergents, cleaners, rust inhibitors, paint thinners, hydrocarbon and chlorinated solvents,  
25 degreasers, acids, caustics, resins, adhesives/cement/sealants and chlorine.

26      51. Upon information and belief, the wastes commonly generated by NATIONAL  
27 IRON WORKS in its operations were abrasive blast waste (with the largest concern being spent  
28 paint containing, among other substances, copper, tributyltin, lead, chromium and zinc); fresh

Gordon & Rees LLP  
101 West Broadway  
Suite 1600  
San Diego, CA 92101

1 paint; bilge waste/oily wastewater; blast wastewater; oils; waste paints; construction repair  
 2 wastes and trash; and miscellaneous wastes consisting of lubricants, grease, fuels, sewage, boiler  
 3 blowdown, condensate, discard, acid wastes, caustic wastes, and aqueous wastes.

4       52. Upon information and belief, NATIONAL IRON WORKS discharged the COCs  
 5 from its leasehold and these discharges have resulted in the contamination of the sediment at the  
 6 Shipyards Sediment Site.

7       **D. MARTINOLICH SHIP BUILDING COMPANY**

8       53. Upon information and belief, from approximately 1940 to 1960, defendant  
 9 MARTINOLICH SHIP BUILDING COMPANY ("MARTINOLICH") owned and operated a  
 10 full service ship construction, modification, repair, and maintenance facility located at 2798  
 11 Harbor Drive (28<sup>th</sup> Street and Harbor Drive) in San Diego, California. MARTINOLICH leased  
 12 the land on which its facility operated from Plaintiff.

13       54. Upon information and belief, MARTINOLICH's primary business was ship  
 14 repair, construction, and maintenance for the NAVY and commercial customers. Site features  
 15 are believed to have included offices, shops, warehouses, concrete platens for steel fabrication, a  
 16 floating dry dock, a graving dock, two shipbuilding ways, and piers providing numerous berthing  
 17 spaces.

18       55. Upon information and belief, the primary industrial processes which  
 19 MARTINOLICH conducted included: surface preparation and paint removal; paint application;  
 20 tank cleaning; mechanical repair/maintenance/installation; structural repair/alteration/assembly;  
 21 integrity/hydrostatic testing; paint equipment cleaning; engine repair/maintenance/installation;  
 22 steel fabrication and machining; electrical repair/maintenance/installation; hydraulic  
 23 repair/maintenance/installation; tank emptying; fueling; shipfitting; carpentry; and  
 24 refurbishing/modernization/cleaning.

25       56. Upon information and belief, the primary materials used by MARTINOLICH in  
 26 its operations included 1) abrasive grit (sometimes consisting of slag from coal-fired boilers and  
 27 often containing iron, aluminum, silicon, calcium oxides, copper, zinc and titanium; also sand,  
 28 cast iron or steel shot is used; enormous amounts are needed to remove paint and it is needed in

Gordon & Rees LLP  
 101 West Broadway  
 Suite 1600  
 San Diego, CA 92101

1 both wet and dry blasting); 2) paint (containing copper, zinc, chromium, lead, and hydrocarbons;  
 2 anticorrosive paint often containing lead and zinc; antifouling paint often containing copper and  
 3 tributyltin); 3) miscellaneous, including oils, grease, fuels, weld, detergents, cleaners, rust  
 4 inhibitors, paint thinners, hydrocarbon and chlorinated solvents, degreasers, acids, caustics,  
 5 resins, adhesives/cement/sealants and chlorine.

6       57. Upon information and belief, the wastes commonly generated by  
 7 MARTINOLICH in its operations were abrasive blast waste (with the largest concern being  
 8 spent paint containing, among other substances, copper, tributyltin, lead, chromium and zinc);  
 9 fresh paint; bilge waste/oily wastewater; blast wastewater; oils; waste paints; construction repair  
 10 wastes and trash; and miscellaneous wastes consisting of lubricants, grease, fuels, sewage, boiler  
 11 blowdown, condensate, discard, acid wastes, caustic wastes, and aqueous wastes.

12       58. Upon information and belief, MARTINOLICH discharged the COCs from its  
 13 leasehold and these discharges have resulted in the contamination of the sediment at the  
 14 Shipyards Sediment Site.

15       E. **BAE SYSTEMS**

16       59. Since 1979, BAE SYSTEMS has owned and operated a ship repair, alteration,  
 17 and overhaul facility on approximately 40 acres of tidelands property located at 2205 East Belt  
 18 Street, Foot of Sampson Street, in San Diego, California ("the BAE Leasehold").

19       60. Since 1979, BAE SYSTEMS has leased the land on which its facility operates  
 20 from the PORT DISTRICT.

21       61. BAE SYSTEMS' business historically has been ship repair and maintenance for  
 22 NAVY and commercial customers. The facilities at BAE SYSTEMS have historically included  
 23 5 piers, 2 floating dry docks and 2 marine railways, which, together with cranes, enable ships to  
 24 be launched or repaired. On-shore facilities have included an abrasive blasting building and a  
 25 paint spray booth. There is an area for steam cleaning/pressure washing vehicles and equipment,  
 26 which includes a sump where effluent is collected and drained to a clarifier that is connected to  
 27 the sewer system. There are also manufacturing and storage areas. BAE SYSTEMS also  
 28 presently manages a solid waste reclamation and recycling area and a hazardous waste

Gordon & Rees LLP  
 101 West Broadway  
 Suite 1600  
 San Diego, CA 92101

1 reclamation facility on the property.

2       62. Upon information and belief, the primary industrial processes which BAE  
3 SYSTEMS has historically conducted include: surface preparation and paint removal; paint  
4 application; tank cleaning; mechanical repair/maintenance/installation; structural  
5 repair/alteration/assembly; integrity/hydrostatic testing; paint equipment cleaning; engine  
6 repair/maintenance/installation; steel fabrication and machining; electrical  
7 repair/maintenance/installation; hydraulic repair/maintenance/installation; tank emptying;  
8 fueling; shipfitting; carpentry; and refurbishing/modernization/cleaning.

9       63. Upon information and belief, the primary materials used by BAE SYSTEMS in  
10 its operations have historically been 1) abrasive grit (sometimes consisting of slag from coal-  
11 fired boilers and often containing iron, aluminum, silicon, calcium oxides, copper, zinc and  
12 titanium; also sand, cast iron or steel shot is used; enormous amounts are needed to remove paint  
13 and it is needed in both wet and dry blasting); 2) paint (containing copper, zinc, chromium, lead,  
14 and hydrocarbons; anticorrosive paint often containing lead and zinc; antifouling paint often  
15 containing copper and tributyltin); 3) miscellaneous, including oils, grease, fuels, weld,  
16 detergents, cleaners, rust inhibitors, paint thinners, hydrocarbon and chlorinated solvents,  
17 degreasers, acids, caustics, resins, adhesives/cement/sealants and chlorine.

18       64. Upon information and belief, the wastes commonly generated by BAE SYSTEMS  
19 historically in its operations have been abrasive blast waste (with the largest concern being spent  
20 paint containing copper, tributyltin, lead, chromium and zinc); fresh paint; bilge waste/oily  
21 wastewater; blast wastewater; oils; waste paints; construction repair wastes and trash; and  
22 miscellaneous wastes consisting of lubricants, grease, fuels, sewage, boiler blowdown,  
23 condensate, discard, acid wastes, caustic wastes, and aqueous wastes.

24       65. Based on the data available for the years 1987-1991, BAE SYSTEMS generated  
25 an average of 178 tons of abrasive blast waste alone per month.

26       66. During numerous inspections starting in the late 1980s, the Regional Board  
27 observed abrasive blast wastes at BAE SYSTEMS' facility deposited in areas where it would  
28 probably be discharged to the Bay via stormwater runoff. Samples of abrasive blast waste and

Gordon & Rees LLP  
101 West Broadway  
Suite 1600  
San Diego, CA 92101

1 other wastes were collected in the vicinity of storm drains or other areas susceptible to being  
 2 transported to the Bay. For example:

3           a.       During an inspection on March 3, 1987, the Regional Board inspector  
 4 reported that "...this facility discharged water from the dry dock to the San Diego Bay";

5           b.       During an inspection on November 9, 1988, the Regional Board inspector  
 6 reported that "Sand blast waste and sewage are being discharged to San Diego Bay".

7       67.   The Regional Board has previously issued Administrative Civil Liability Orders  
 8 against BAE SYSTEMS for discharges to the Bay, including:

9           a.       The Regional Board issued Complaint 89-02 against BAE SYSTEMS for  
 10 discharge of abrasive grit waste and raw sewage to San Diego Bay. The abrasive grit waste  
 11 contained elevated levels of arsenic, chromium, lead, and zinc and hazardous levels of copper.

12          b.       The Regional Board issued Complaint 2001-138 to BAE SYSTEMS for  
 13 violation of storm water runoff requirements of its NPDES permit. Storm water samples  
 14 exceeded the permitted levels for copper and zinc.

15       68.   On April 30, 1996, the Natural Resources Defense Counsel, Inc., San Diego  
 16 Baykeeper, and Kenneth J. Moser brought Clean Water Act legal action in this Court against  
 17 BAE SYSTEMS for, *inter alia*, violating its NPDES permit requirements by discharging  
 18 unlawful amounts of pollutants into San Diego Bay.

19       69.   On September 7, 1999, this Court issued its findings of fact and conclusions of  
 20 law, finding that convincing evidence showed, *inter alia*, that BAE SYSTEMS' reports  
 21 demonstrated a pattern of poor housekeeping and showed that violations, when reported, were  
 22 not remedied timely; that BAE SYSTEMS' implementation of its plans had led to significant  
 23 contributions of pollutants to BAE SYSTEMS' leasehold; that substantial quantities of pollutants  
 24 from BAE SYSTEMS' paint-blasting operations had entered San Diego Bay in BAE SYSTEMS'  
 25 storm water discharges; and that BAE SYSTEMS' failure to implement its storm water plans  
 26 adequately was contributing to and perpetuating the contamination of its leasehold. The findings  
 27 and ruling was appealed to the Ninth Circuit Court of Appeals, which did not overturn any of the  
 28 rulings of this Court. The United States Supreme Court denied the appeal.

Gordon & Rees LLP  
 101 West Broadway  
 Suite 1600  
 San Diego, CA 92101

1       70. The Regional Board has alleged in Tentative Order R9-2005-0126 that BAE  
2 SYSTEMS has caused or permitted waste from its shipyard operations to be discharged into the  
3 Bay in violation of waste discharge requirements, and discharged or deposited waste where it  
4 was discharged into the Bay creating, or threatening to create, a condition of pollution or  
5 nuisance. The Regional Board has alleged that BAE SYSTEMS has violated Water Code  
6 section 13304 and violated its NPDES permit requirements under the Clean Water Act section  
7 402.

8       71. Upon information and belief, BAE SYSTEMS has intentionally or accidentally  
9 discharged the COCs from its leasehold and these discharges have resulted in the contamination  
10 of the sediment at the Shipyards Sediment Site.

11     **F. SAN DIEGO MARINE CONSTRUCTION COMPANY & THE STAR AND**  
12     **CRESCENT COMPANIES**

13       72. Plaintiff leased to the SDMCC DEFENDANTS certain property at the foot of  
14 Sampson street from 1914 to 1962.

15       73. From 1962 to July 1972, the PORT DISTRICT leased this property to the  
16 SDMCC DEFENDANTS.

17       74. Upon information and belief, the facility owned and operated by the SDMCC  
18 DEFENDANTS was historically a ship repair and construction facility for NAVY and  
19 commercial customers. The facility included 2 floating dry docks and 3 marine railways, which,  
20 together with cranes, enabled ships to be launched or repaired.

21       75. Upon information and belief, the primary industrial processes which the SDMCC  
22 DEFENDANTS likely conducted include: surface preparation and paint removal; paint  
23 application; tank cleaning; mechanical repair/maintenance/installation; structural  
24 repair/alteration/assembly; integrity/hydrostatic testing; paint equipment cleaning; engine  
25 repair/maintenance/installation; steel fabrication and machining; electrical  
26 repair/maintenance/installation; hydraulic repair/maintenance/installation; tank emptying;  
27 fueling; shipfitting; carpentry; and refurbishing/modernization/cleaning.

28       76. Upon information and belief, the primary materials believed to have been used by

Gordon & Rees LLP  
101 West Broadway  
Suite 1600  
San Diego, CA 92101

1 the SDMCC DEFENDANTS in their operations, based on typical materials used in the industry,  
 2 are 1) abrasive grit (sometimes consisting of slag from coal-fired boilers and often containing  
 3 iron, aluminum, silicon, calcium oxides, copper, zinc and titanium; also sand, cast iron or steel  
 4 shot is used; enormous amounts are needed to remove paint and it is needed in both wet and dry  
 5 blasting); 2) paint (containing copper, zinc, chromium, lead, and hydrocarbons; anticorrosive  
 6 paint often containing lead and zinc; antifouling paint often containing copper and tributyltin); 3)  
 7 miscellaneous, including oils, grease, fuels, weld, detergents, cleaners, rust inhibitors, paint  
 8 thinners, hydrocarbon and chlorinated solvents, degreasers, acids, caustics, resins,  
 9 adhesives/cement/sealants and chlorine.

10       77. Upon information and belief, the wastes believed to have been generated by the  
 11 SDMCC DEFENDANTS in their operations, based on those generated by the above-listed  
 12 shipyard activities, are abrasive blast waste (with the largest concern being spent paint containing  
 13 copper, tributyltin, lead, chromium and zinc); fresh paint; bilge waste/oily wastewater; blast  
 14 wastewater; oils; waste paints; construction repair wastes and trash; and miscellaneous wastes  
 15 consisting of lubricants, grease, fuels, sewage, boiler blowdown, condensate, discard, acid  
 16 wastes, caustic wastes, and aqueous wastes.

17       78. In March 1972, the Regional Board initiated an investigation to determine the  
 18 amount of and kinds of pollutants that entered San Diego Bay from shipbuilding and repair  
 19 facilities, and the possible effects that pollution could have on beneficial uses of the Bay. All  
 20 shipbuilding and repair facilities were inspected, including SDMCC. The report noted, *inter*  
*alia*, the following conditions from the year 1971:

22           a. SDMCC constructed 6 new ships and refinished 70 ships in 1971.  
 23 Approximately 20-50% of the ships were sandblasted. Approximately 8,000 gallons of paint and  
 24 primer containing copper and tributyltin were used. Air sand blasting with black sand was used  
 25 to strip vessels to bare metal in the dry docks and on the railways;

26           b. The SDMCC DEFENDANTS' facility was located immediately adjacent  
 27 to the Bay, and wastes from the facility were conveyed to the Bay by water flows, by becoming  
 28 airborne, or by falling directly into the Bay;

Gordon & Rees LLP  
 101 West Broadway  
 Suite 1600  
 San Diego, CA 92101

1       79. The Regional Board has alleged in Tentative Order R9-2005-0126 that SDMCC  
 2 caused or permitted waste from its shipyard operations to be discharged into the Bay creating, or  
 3 threatening to create, a condition of pollution or nuisance. The Regional Board has alleged that  
 4 SDMCC has violated Water Code section 13304.

5       80. Upon information and belief, SDMCC has intentionally or accidentally  
 6 discharged the COCs from its leasehold and these discharges have resulted in the contamination  
 7 of the sediment at the Shipyards Sediment Site.

8       **G. CAMPBELL INDUSTRIES, MCCSD, AND SAN DIEGO MARINE**  
 9       **CORPORATION**

10      81. Upon information and belief, from at least 1972 (if not earlier) to 1979, the  
 11 CAMPBELL DEFENDANTS owned and operated a ship repair, alteration, and overhaul facility  
 12 on approximately 40 acres of tidelands property on or about 2205 East Belt Street, Foot of  
 13 Sampson Street, in San Diego, California, within or adjacent to the BAE Leasehold. The  
 14 CAMPBELL DEFENDANTS leased this property from the PORT DISTRICT.

15      82. Upon information and belief, the CAMPBELL DEFENDANTS' facility included  
 16 2 floating dry docks and 3 marine railways, which, together with cranes, enable ships to be  
 17 launched or repaired.

18      83. Upon information and belief, the primary industrial processes which the  
 19 CAMPBELL DEFENDANTS likely conducted, based upon typical ship construction and repair  
 20 industry activities, include: surface preparation and paint removal; paint application; tank  
 21 cleaning; mechanical repair/maintenance/installation; structural repair/alteration/assembly;  
 22 integrity/hydrostatic testing; paint equipment cleaning; engine repair/maintenance/installation;  
 23 steel fabrication and machining; electrical repair/maintenance/installation; hydraulic  
 24 repair/maintenance/installation; tank emptying; fueling; shipfitting; carpentry; and  
 25 refurbishing/modernization/cleaning.

26      84. Upon information and belief, the primary materials believed to have been used by  
 27 the CAMPBELL DEFENDANTS in its operations, based on typical materials used in the  
 28 industry, are 1) abrasive grit (sometimes consisting of slag from coal-fired boilers and often

Gordon & Rees LLP  
 101 West Broadway  
 Suite 1600  
 San Diego, CA 92101

1 containing iron, aluminum, silicon, calcium oxides, copper, zinc and titanium; also sand, cast  
2 iron or steel shot is used; enormous amounts are needed to remove paint and it is needed in both  
3 wet and dry blasting); 2) paint (containing copper, zinc, chromium, lead, and hydrocarbons;  
4 anticorrosive paint often contains lead and zinc; antifouling paint often contains copper and  
5 tributyltin); 3) miscellaneous, including oils, grease, fuels, weld, detergents, cleaners, rust  
6 inhibitors, paint thinners, hydrocarbon and chlorinated solvents, degreasers, acids, caustics,  
7 resins, adhesives/cement/sealants and chlorine.

8       85. Upon information and belief, the wastes believed to have been generated by the  
9 CAMPBELL DEFENDANTS in its operations, based on those generated by the above-listed  
10 shipyard activities, are abrasive blast waste (with the largest concern being spent paint containing  
11 copper, tributyltin, lead, chromium and zinc); fresh paint; bilge waste/oily wastewater; blast  
12 wastewater; oils; waste paints; construction repair wastes and trash; and miscellaneous wastes  
13 consisting of lubricants, grease, fuels, sewage, boiler blowdown, condensate, discard, acid  
14 wastes, caustic wastes, and aqueous wastes.

15       86. Data from the PORT DISTRICT indicate that historical operations at the  
16 CAMPBELL DEFENDANTS' facility included:

- 17           a.      Use of formaldehyde and arsenic in pretreated wood at the wood shop;
- 18           b.      Performance of blasting, welding and painting activities for Navy contract  
19 work in the blasting area;
- 20           c.      Use of a dust suppression system for the blasting house, which consisted  
21 of blowers directed to the Bay with a water spray to cause blast dust to settle in the water;
- 22           d.      Discharge of all wastes generated on the dry dock to the Bay, including  
23 blast grit and paint.

24       87. In 1973, an undetermined amount of fuel was released to the Bay from the  
25 CAMPBELL DEFENDANTS' leasehold, resulting in temporary site closure.

26       88. The Regional Board has alleged in Tentative Order R9-2005-0126 that the entities  
27 operating at the CAMPBELL DEFENDANTS' facility caused or permitted waste from its  
28 shipyard operations to be discharged into the Bay in violation of waste discharge requirements,

Gordon & Rees LLP  
101 West Broadway  
Suite 1600  
San Diego, CA 92101

1 and discharged or deposited waste where it was discharged into the Bay creating, or threatening  
 2 to create, a condition of pollution or nuisance. The Regional Board has alleged that  
 3 CAMPBELL violated Water Code section 13304 and violated its NPDES permit requirements  
 4 under the Clean Water Act section 402.

5       89. Upon information and belief, the CAMPBELL DEFENDANTS have intentionally  
 6 or accidentally discharged the COCs from its leasehold and these discharges have resulted in the  
 7 contamination of the sediment at the Shipyards Sediment Site.

8       **H. SDG&E**

9       90. Defendant SDG&E, a subsidiary of Sempra Energy Company, owned and  
 10 operated the Silvergate Power Plant along the north side of the BAE Leasehold from  
 11 approximately 1943 to the 1990s. The plant ceased active operations in approximately 1984 and  
 12 was decommissioned in 2004.

13       91. Upon information and belief, the Silvergate Power Plant included 4 steam turbine  
 14 electrical generators. The boilers initially burned fuel oil, and in later years were converted to  
 15 burn both natural gas and fuel oil. There was also an electrical switchyard adjacent to the plant  
 16 itself. The facility had transformers onsite.

17       92. Upon information and belief, as part of the plant's operations, SDG&E  
 18 maintained an easement to San Diego Bay for cooling water discharge tunnels ("CW tunnels") to  
 19 deliver and remove water used for cooling the turbines. The turbine sump pumps discharged to  
 20 the CW tunnels. Bilge water was also piped to the CW tunnels. The CW tunnels had flow rates  
 21 of 120-180 million gallons per day. The discharge CW tunnel was located in close proximity to  
 22 the property line with the BAE Leasehold.

23       93. Upon information and belief, there were also at least 2 wastewater  
 24 settling/evaporation ponds and 2 subgrade oil separators on the SDG&E easement, within close  
 25 proximity to the Bay. Basement bilge water from the boiler side of the plant was pumped to a  
 26 pond(s) for settling and evaporation, and some of that water was discharged to the Bay.  
 27 Historical photographs indicate a surface spill at "Pond A" occurred on or about 1952 when a  
 28 plug in piping led to overflow of liquid onto the adjacent ground, which photographs indicate

Gordon & Rees LLP  
 101 West Broadway  
 Suite 1600  
 San Diego, CA 92101

1 flowed to the Bay. "Pond B" was used from at least 1966-1973 as an oil-water settling pond.  
2 There was also an area referred to as "Nobel's Lake," which may have been "Pond B," which  
3 received discharges from all sources in the north side of the plant, including the fuel oil pump  
4 room sump pump, and possibly the turbine room sump pumps, control rooms, generator vaults in  
5 the switchyard, electrical repair, maintenance and machining areas, and rinewater from cleaning  
6 out drums containing PCBs. As of 1974, "Nobel's Lake" was filled to the brim and contained an  
7 11 foot deep mixture of oil and earth.

8       94. Upon information and belief, the Silvergate Power Plant's switchyard and plant  
9 itself were sources of PCBs:

10       a. In the switchyard, the following equipment likely contained PCB fluids:  
11 75 oil circuit breaker tanks, 4 transformers, and the main and auxillary transformers for  
12 Generator Units 1-4. The presence of PCBs at the site was documented during the Underground  
13 Tank Storage program on or about 2006.

14       b. In the power plant itself, the following equipment in the turbine room and  
15 on the cooling water deck likely contained PCB fluids: 4 Steam Turbine Generator Sets, 8  
16 (2500-3000 gallon) Turbine Lubricating Oil tanks, 2 power and 2 lighting transformers near each  
17 of Generator Units 1 and 2 on the cooling water deck. Shop areas conducting electrical repairs,  
18 maintenance and machining also could have been PCB sources. Capacitors, switches, reclosers,  
19 wiring insulation, lube oil coolers, condensate pumps, overhead cranes and hoists are also  
20 potential sources.

21       95. Upon information and belief, Studies indicate that steam turbine  
22 hydraulic/lubricating oil loss from power plants on an annual basis ranges from 5-30%, with the  
23 average annual loss in the United States 7-10%.

24       96. Upon information and belief, Case studies indicate that PCBs are most commonly  
25 found on and around the oil lubrication systems, former station transformer areas and power-  
26 generation equipment at plants, and that PCBs were found in turbine generator lubrication oil  
27 because of the use of the same as a lubricant throughout plants.

28       97. Upon information and belief, there were multiple transport pathways for PCBs to

Gordon & Rees LLP  
101 West Broadway  
Suite 1600  
San Diego, CA 92101

1 be discharged from the Silvergate Power Plant to San Diego Bay:

2           a.     CW Tunnel System: The turbine sump pumps discharged to the CW  
 3 Tunnel, which discharged to the Bay immediately north of the current BAE SYSTEMS  
 4 leasehold. The turbine sump pumps were likely recipients of discharges from turbine generator  
 5 lubrication/hydraulic systems, overhead crane hydraulic system, or electrical gear (capacitors,  
 6 transformers, reclosers, switchers), which contained PCBs. Bilge water was also piped to the  
 7 CW tunnels. The CW tunnel system was not a closed system.

8           b.     Ponds, including "Nobel's Lake": "Pond A" had a documented overflow  
 9 in 1952 which reached the Bay near the property line with the current BAE SYSTEMS  
 10 leasehold. This overflow likely contained PCBs, given that PCB containing oils were used at  
 11 power plants on a widespread basis in this time frame. "Pond B" was used from at least 1966-  
 12 1973 as an oil-water settling pond, located a few hundred feet from the Bay, also near the  
 13 property line with the BAE Leasehold. "Nobel's Lake," which may have been "Pond B,"  
 14 received discharges from all sources in the north side of the plant, including the fuel oil pump  
 15 room sump pump, and possibly the turbine room sump pumps, control rooms, generator vaults in  
 16 the switchyard, electrical repair, maintenance and machining areas, and rinsewater from cleaning  
 17 out drums containing PCBs. Photographs indicate surface drainage around the Nobel's Lake  
 18 area in the 1950s and document removals of "sludge" and "muck" from it which was simply  
 19 placed in a hole nearby, all in very close proximity to the Bay. As of 1974, "Nobel's Lake" was  
 20 filled to the brim and contained an 11 foot deep mixture of "oil and earth." Photographs and  
 21 plant diagrams indicate that Nobel's Lake itself drained into the CW discharge tunnel or directly  
 22 into the Bay through an outlet pipe. Soil samples taken in the vicinity of Pond B/Nobel's Lake  
 23 in 1995 indicate elevated levels of PCBs, chromium, copper, lead, nickel and zinc.

24           c.     Floor drains: An undated SDG&E training manual states that "... floor  
 25 drains are in areas where large amounts of oil may be spilled."

26           d.     Surface runoff from switchyard: There was the potential for runoff of  
 27 sediments containing PCBs during precipitation events, directly to the Bay or to the Bay through  
 28 one of Plaintiff's MS4 outfalls. On information and belief, transformers in the switchyard were

Gordon & Rees LLP  
 101 West Broadway  
 Suite 1600  
 San Diego, CA 92101

1 not contained within concrete sumps and there were not secondary containment measures for oil  
 2 storage units until the 1970s.

3       98. Upon information and belief, in 2006, during closure of SDG&E's underground  
 4 storage tanks, PCBs were detected in the soil in all 18 samples taken around at the facility.  
 5 Eleven of the samples had PCBs above 1000 ug/kg. The 3 highest samples had concentrations of  
 6 125,000 ug/kg, 14,700 ug/kg and 34,700 ug/kg. Copper, lead and zinc were also detected. The  
 7 Regional Board found in its Tentative Order R9-205-0126 that the PCBs and metals deposited in  
 8 the soil by SDG&E were such that they were, or probably would be, discharged to the Bay via  
 9 storm water runoff.

10      99. In 2005, Plaintiff observed an illegal discharge into its MS4 catch basin on the  
 11 north side of Sampson Street, immediately to the east of BAE SYSTEMS' parking lot and the  
 12 SDG&E Silvergate Power Plant. Plaintiff took sampling of the inside and base of the six inch  
 13 lateral entering the basin from the former plant leasehold, the base of the 12 inch lateral entering  
 14 the basin from an area draining water from the facility, and from the 18 inch pipe exiting the  
 15 basin and conveying to the Bay at the Shipyard Sediment Site. The results indicated the  
 16 presence of PCBs and PAHs entering the storm water system from the former plant leasehold,  
 17 and exiting the storm drain system to the Bay. Plaintiff issued a Notice of Violation to SDG&E.

18      100. The Regional Board has alleged in Tentative Order R9-2005-0126 that SDG&E  
 19 caused or permitted waste from its power plant operations to be discharged into the Bay in  
 20 violation of waste discharge requirements, and discharged or deposited waste where it was  
 21 discharged into the Bay creating, or threatening to create, a condition of pollution or nuisance.  
 22 The Regional Board has alleged that SDG&E has violated Water Code section 13304 and  
 23 violated its NPDES permit requirements under the Clean Water Act section 402.

24      101. Upon information and belief, SDG&E has intentionally or accidentally discharged  
 25 the COCs from its leasehold and these discharges have resulted in the contamination of the  
 26 sediment at the Shipyards Sediment Site.

27 **I. UNITED STATES NAVY**

28      102. From 1921 to present, NAVY has provided shore support and pier-side berthing

Gordon & Rees LLP  
 101 West Broadway  
 Suite 1600  
 San Diego, CA 92101

1 services to U.S. Pacific fleet vessels at Naval Station San Diego ("NAVSTA"), which it owns  
 2 and operates, located at 3445 Surface Navy Boulevard.

3       103. NAVSTA currently occupies 1,029 acres of land and 326 water acres adjacent to  
 4 San Diego Bay to the west, and Chollas Creek north near Pier 1. It is immediately south of and  
 5 adjacent to the Shipyard Sediment Site. NAVSTA's present leasehold includes a 24,653 square  
 6 foot parcel north of and immediately adjacent to Chollas Creek, at the south end of 28<sup>th</sup> Street.

7       104. Between 1938 and 1956, NAVSTA's leasehold also included the 28<sup>th</sup> Street  
 8 Shore Boat Landing Station, located at the south end of the present day NASSCO leasehold at  
 9 the foot of 28<sup>th</sup> Street, including the 28<sup>th</sup> Street Pier. Upon information and belief, at this  
 10 location, NAVY conducted operations similar to a small boatyard, including solvent cleaning  
 11 and degreasing of vessel parts and surfaces, abrasive blasting and scraping for paint removal and  
 12 surface preparations, metal plating, and surface finishing and painting.

13       105. Upon information and belief, NAVSTA historically has provided supply and  
 14 maintenance logistical support to numerous U.S. Navy vessels. NAVSTA was used extensively  
 15 in the 1920s and 1930s for repair and maintenance of U.S. Navy Destroyer vessels. The base was  
 16 rapidly expanded in the 1930s and 1940s. From 1943 to 1945, more than 5,000 ships were sent  
 17 to the base for conversion, overhaul, battle damage, repair, or maintenance. Almost half of these  
 18 ships were dry docked. In the mid-1940s, the base added another 823 acres, 200 buildings, a  
 19 1,700 marine railway, a cruiser graving dry dock, five large repair piers, a quay wall totally  
 20 28,000 feet of berthing space, and extensive industrial repair facilities. NAVSTA is currently  
 21 home port for approximately 60 naval vessels and 50 separate commands.

22       106. Upon information and belief, a number of historical activities at NAVSTA  
 23 resulted in the discharge of hazardous substances to the San Diego Bay, including:

24           a.      Former ship repair basins: Many ship repair operations were conducted in  
 25 4 basins used as ship repair wet docks between 1943-1945, when over 5,000 ships were sent  
 26 there for conversion, overhaul and repair. Thereafter, until 1972, at least 2 basins were used as  
 27 informal disposal sites for hazardous and non-hazardous solid waste. Chemical constituents  
 28 identified in these basins in the 1990s included lubricants, oils, and PCBs. In 1998, 16 tons of

1 PCB and PAH impacted soil was removed as part of an initial cleanup action.

2           b.       Mole pier: Constructed in 1942, materials such as creosote-coated pier  
3 pilings, lumber, refuse concrete, waste paints, gasoline, oil and diesel fuel were burned at the site  
4 between 1945 and 1972. Trucks and heavy equipment were decontaminated here by spraying  
5 them with diesel fuel and dunking them in Paleta Creek, which flows to the Bay. It is estimated  
6 that approximately 500,000 gallons of fuel was sprayed, burned or buried in this area  
7 historically.

8           c.       Salvage Yard: Materials handled by this yard between 1943 and  
9 approximately 1975 include transformers containing PCBs, mercury, electrolytes from old  
10 batteries, drummed petroleum wastes, solvents and thinners, and demolition debris. It is  
11 estimated that 100-200 drums of waste lubricating oils, lubricants and solvents were transported  
12 here for handling. Liquids were incinerated, poured onto the ground, or recycled. Pollutants  
13 could have migrated to the Bay via Paleta Creek or surface water runoff.

14           d.       Defense Property Disposal Office Storage Yard: Used between 1943  
15 through 1981, this site was routinely oiled as a dust control measure prior to 1975, with some  
16 35,000 to 75,000 gallons of waste petroleum, oils and lubricants. Chemical constituents  
17 identified here in the 1990s include petroleum, PCBs and metals. Hazardous substances  
18 migrated to the Bay via Paleta Creek or surface water runoff.

19           e.       Firefighting training facility: Between 1945 and 1995, NAVY operated  
20 this facility near its Pier 8. Training fires were lit regularly using petroleum hydrocarbons,  
21 including approximately 3500 gallons per week of jet propellant grade 5 and gasoline. Prior to  
22 1972, there was no pollution control equipment and chemicals could have migrated to the Bay.  
23 Contamination was identified at the site in the early 1990s and extraction systems have  
24 reportedly removed some 15,000 gallons of free product.

25           f.       PCB Storage Facility Electrical Storage Yard: From 1981 through 1994,  
26 NAVY operated a PCB storage facility near Paleta Creek, approximately 1000 feet from the Bay.  
27 The area was used primarily for maintenance of electrical equipment, including draining of  
28 transformer fluids and storage of fluids containing PCBs. PCBs were not segregated from other

Gordon & Rees LLP  
101 West Broadway  
Suite 1600  
San Diego, CA 92101

1 fluids until the late 1980s. Waste oil likely containing PCBs was applied to the ground for dust  
2 and weed suppression. PCB impacted soil was removed from the site and a nearby storm drain  
3 in the mid-1990s.

4 g. Material Storage Yard: The site was used between 1939 and 1995 as an  
5 unpaved storage yard for metal finishing, preservation and packaging at Building 321. In the  
6 1990s, metals, PAHs and PCBs were identified in soil at the site.

7 h. Brinser Street parking area: NAVY constructed floating dry docks and  
8 barges here near its Pier 7 between 1941 and 1945. Facilities included 2 shallow creosote dip  
9 ponds used to treat lumber on the site. Soil investigations have revealed presence of petroleum  
10 products, PAHs and metals, among others. Surface water run off could have transported  
11 pollutants to the Bay.

12 i. Drydock sandblast area: The drydock sandblast grit area is located  
13 immediately east of Piers 5 and 6. The site has been used for overhaul and maintenance of ships,  
14 repair of ship components and contractor equipment since 1942. Operations here, which  
15 continue to present, include sandblasting and painting. Copper abrasive blast material was used  
16 to remove anticorrosive and antifouling paint from ship hulls. A railcar and silo transported and  
17 stored the sandblast grit. Open air sandblasting took place until 1993. In October 1992, visible  
18 surface contamination was removed, and the elevated levels of arsenic, iron, lead, manganese,  
19 copper, and nickel, among others, were detected.

20 j. Historic operations at present NASSCO leasehold: Between 1938 and  
21 1956, NAVY operated the 28<sup>th</sup> Street Shore Boat Landing Station, currently part of the NASSCO  
22 leasehold, consisting of a finger pier and various machine and electrical shops and stores. On  
23 information and belief, the activities conducted were most likely similar to those at a small boat  
24 yard. Typically, such activities include scrubbing boat hulls, blasting, and painting. Paints used  
25 typically include copper, arsenic, and mercury. Activities historically occur outside, close to  
26 receiving waters. In its 1970s investigation of shipyards, the Regional Board concluded that in  
27 San Diego Bay, heavy metal concentrations were higher in sediment near boatyards and  
28 shipyards. Core sampling in the area of these former NAVY operations indicates that there are

Gordon & Rees LLP  
101 West Broadway  
Suite 1600  
San Diego, CA 92101

1 metals, tributyltin and PCBs likely attributable to NAVY's operations.

2       107. Upon information and belief, current NAVY operations on the wetside also likely  
3 discharge pollutants into San Diego Bay from in and around NAVSTA's 13 piers berth ships,  
4 barges and support vessels. Berth-side repair and maintenance conducted is believed to include  
5 abrasive blasting, hydro-blasting, metal grinding, painting, tank cleaning, removal of bilge and  
6 ballast water, removal of anti-fouling paint, sheet metal work, electrical work, mechanical repair,  
7 engine repair, hull repair and sewage disposal. More complex similar activities are typically  
8 conducted at the graving dock or floating dry dock. Discharges include industrial process water  
9 or stormwater contaminated with abrasive blast material, paint, oils, lubricants, fuels and  
10 solvents. NAVY ship movements and tidal flows work to distribute pollutants from NAVSTA to  
11 the Shipyard Sediment Site.

12       108. On information and belief, additionally, NAVY currently and historically has  
13 many of its ships and other vessels serviced at the NASSCO leasehold operations and the BAE  
14 SYSTEMS leasehold operations. On information and belief, NAVY would provide detailed  
15 specifications for all repair, overhaul, construction and maintenance work on its ships to  
16 NASSCO, NATIONAL STEEL & SHIPBUILDING CORPORATION, NATIONAL IRON  
17 WORKS, MARTINOLICH SHIP BUILDING COMPANY, BAE SYSTEMS, the SDMCC  
18 DEFENDANTS, and the CAMPBELL DEFENDANTS. Upon information and belief, this  
19 included, but was not limited to, what type of antifouling and marine paints to use on NAVY  
20 ships, which were NAVY or U.S. Military formulations; other painting specifications for NAVY  
21 ships; how to conduct abrasive blasting and scraping on ships; and how to conduct hull cleaning  
22 on ships. On information and belief, NAVY has and had its own offices and/or conference  
23 rooms and/or NAVY operated facilities at the current NASSCO and BAE SYSTEMS leaseholds,  
24 both presently and historically. On information and belief, NAVY personnel on the ships and  
25 vessels also themselves conducted such repair, overhaul, construction and maintenance work on  
26 NAVY ships while those ships were docked at the facilities owned and operated by NASSCO,  
27 NATIONAL STEEL & SHIPBUILDING CORPORATION, NATIONAL IRON WORKS,  
28 MARTINOLICH SHIP BUILDING COMPANY, BAE SYSTEMS, the SDMCC

Gordon & Rees LLP  
101 West Broadway  
Suite 1600  
San Diego, CA 92101

1 DEFENDANTS and the CAMPBELL DEFENDANTS. Discharges from this work on NAVY  
 2 ships and vessels from this work, which NAVY was aware of and intended via its issuance of  
 3 detailed specifications for this work, and which NAVY itself caused from its own work on these  
 4 ships and vessels while docked at these shipyards, likely contributed to the discharge of  
 5 hazardous substances into the Shipyard Sediment Site, including metals (arsenic, cadmium,  
 6 copper, lead, mercury, zinc), tributyltins, PAHs, and PCBs.

7       109. Upon information and belief, NAVSTA's dryside consists of facilities east of  
 8 Harbor Drive, and contains at least 8 of its own MS4 storm drains. NAVY owns and operates its  
 9 own MS4 storm water conveyance system. Some 266 acres of NAVSTA drain directly to  
 10 Chollas Creek.

11       110. The Regional Board has alleged in Tentative Order R9-2005-0126 that NAVY  
 12 has caused or permitted the discharge of pollutants to the San Diego Bay in violation of its  
 13 NPDES permit, including excessive concentrations of copper, lead and zinc.

14       111. The Regional Board has further alleged in Tentative Order R9-2005-0126 that  
 15 NAVY caused or permitted waste from its NAVSTA operations to be discharged into the Bay,  
 16 via storm water, tides and ship movement, and discharged directly into the Shipyard Sediment  
 17 Site through its prior operations at the 28<sup>th</sup> Street Shore Boat Landing Station, in violation of  
 18 waste discharge requirements, and discharged or deposited waste where it was discharged into  
 19 the Bay creating, or threatening to create, a condition of pollution or nuisance. The Regional  
 20 Board has alleged that NAVY has violated Water Code section 13304 and violated its NPDES  
 21 permit requirements under the Clean Water Act section 402.

22       112. NAVY's own studies suggest that a chronic substantial source of PAHs to San  
 23 Diego Bay is from creosote treated pilings, like those on NAVY's Mole pier.

24       113. Upon information and belief, the NAVY has intentionally or accidentally  
 25 discharged the COCs from its operations and these discharges have resulted in the contamination  
 26 of the sediment at the Shipyards Sediment Site.

27       J. **PORT DISTRICT**

28       114. Since 1962, the PORT DISTRICT has had an ownership interest, as a public

Gordon & Rees LLP  
 101 West Broadway  
 Suite 1600  
 San Diego, CA 92101

1 trustee and landlord, in the NASSCO and BAE Leaseholds, and in the property formerly leased  
 2 to the SDMCC DEFENDANTS and the CAMPBELL DEFENDANTS, as well as in an easement  
 3 for the cooling water tunnels from SDG&E's Silvergate Powerplant.

4       115. The State of California holds title to the navigable waterways and the land  
 5 beneath them as a trustee for the public. The State's power to control, regulate and utilize the  
 6 navigable waterways within the terms of the trust is absolute except as limited by the supervisory  
 7 power of the federal government. Under the San Diego Unified Port District Act ("the Act"), the  
 8 state of California delegated its authority to manage and control San Diego Bay to the PORT  
 9 DISTRICT. The Act authorizes the PORT DISTRICT to make and enforce all necessary rules  
 10 and regulations regarding the tidelands within its jurisdiction. Accordingly, the PORT  
 11 DISTRICT had regulatory land use authority over the property it held in trust and leased to  
 12 NAASCO, BAE SYSTEMS, the SDMCC DEFENDANTS, the CAMPBELL DEFENDANTS,  
 13 and SDG&E.

14       116. Upon information and belief, the PORT DISTRICT had, through its interactions  
 15 with the Regional Board over the years, known of the likelihood of intentional and/or accidental  
 16 discharges of hazardous substances from NASSCO, BAE SYSTEMS, the SDMCC  
 17 DEFENDANTS, the CAMPBELL DEFENDANTS, and SDG&E contributing to the  
 18 accumulations of hazardous substances in the Shipyards Sediment Site area. Despite this  
 19 knowledge, the PORT DISTRICT did not exercise its regulatory land use authority to prevent the  
 20 discharges of hazardous substances.

21       117. Upon information and belief, the PORT DISTRICT has had the legal authority  
 22 under its lease agreements with its lessees, including Defendants discussed above, to impose  
 23 controls that could prevent or reduce the Defendant lessees' discharges of hazardous substances:

24           a.       Lease agreements between PORT DISTRICT and its tenants typically  
 25 contained terms that obligated its tenants to "abide by and conform to . . . any applicable laws of  
 26 the State of California and Federal Government."

27           b.       Defendant PORT DISTRICT's leases also required that its tenants keep  
 28 the leased premises in a clean and sanitary condition, free and clear of waste.

Gordon & Rees LLP  
 101 West Broadway  
 Suite 1600  
 San Diego, CA 92101

c. The leases also authorized PORT DISTRICT to enter and inspect the premises at any time during normal business hours.

d. The leases authorized PORT DISTRICT to terminate the lease after 60 days written notice if the tenant defaulted in performance of the lease provisions.

118. The Regional Board alleged, in Tentative Order R9-2005-0126, that the above cited lease terms would be sufficient to base a finding that the PORT DISTRICT had the requisite degree of control over its tenants' activities to show that PORT DISTRICT caused or permitted waste to be discharged into San Diego Bay, creating a condition of pollution at the Shipyard Sediment Site.

119. Upon information and belief, the PORT DISTRICT's tenants at the NAASCO and BAE Leaseholds have intentionally and/or accidentally discharged the COCs from their operations and these discharges have resulted in the contamination of the sediment at the Shipyards Sediment Site.

## **FIRST CAUSE OF ACTION**

#### **(Cost Recovery Under CERCLA against all Defendants)**

120. Plaintiff realleges all prior paragraphs and incorporates them by reference.

17        121. The Comprehensive Environmental Response, Compensation, and Liability Act  
18 ("CERCLA"), CERCLA Section 107(a), 42 U.S.C. § 9607(a), provides as follows:

(1) the owner or operator of a . . . facility,

(2) any person who at the time of disposal of any hazardous substance owned or operated any facility at which such hazardous substances were disposed of, [or]

(3) any person who . . . arranged for disposal or treatment . . . of hazardous substances . . . at any facility...

(4) .... from which there is a release, or threatened release which causes the incurrence of response costs, of a hazardous substance, shall be liable for –

1                             (B) any other necessary costs of response incurred by any other person consistent  
2                             with the national contingency plan.

3                         122. As detailed in the general allegations above, each Defendant qualifies as a  
4                             “covered person” as defined by Section 107(a) of CERCLA, 42 U.S.C. § 9607(a).

5                         123. The chemicals and substances which Defendants used, stored, disposed of,  
6                             discharged and released into the Shipyard Sediment Site were “hazardous substances” within the  
7                             meaning of CERCLA Section 101(14), 42 U.S.C. § 9601(14). Such hazardous substances  
8                             included the COCs.

9                         124. A “release” or “threatened release” of hazardous substances within the meaning  
10                             of CERCLA Section 101(22), 42 U.S.C. § 9601(22), has occurred at the Shipyard Sediment Site  
11                             from each of Defendants’ ownership, operations or arrangements for disposal of hazardous  
12                             substances at facilities at or adjacent to the Shipyard Sediment Site. Defendants, and each of  
13                             them, conducted themselves in their ownership and/or operations and/or disposal arrangement  
14                             activities at or around the Shipyard Sediment Site so as to directly, proximately and/or causally  
15                             contribute to the damages as alleged herein.

16                         125. The release(s) or threatened release(s) have occurred from a “facility” or facilities  
17                             into the Shipyard Sediment Site within the meaning of CERCLA Section 101(9), 42 U.S.C. §  
18                             9601(9).

19                         126. As a result of the “release(s)” and/or threatened “releases(s)” of “hazardous  
20                             substances,” by Defendants, Plaintiff has conducted and is conducting a “response” within the  
21                             meaning of CERCLA Section 101(25), 42 U.S.C. § 9601(25), and has incurred and will incur  
22                             response costs.

23                         127. Plaintiff has incurred, and will continue to incur, substantial costs consistent with  
24                             the National Contingency Plan to investigate and remediate releases and/or threatened releases of  
25                             hazardous substances in the environment at and around the Site.

26                         128. Plaintiff requests that judgment be entered in its favor and against Defendants  
27                             pursuant to 42 U.S.C. § 9607(a) for all response costs that Plaintiff has incurred and will in the

Gordon & Rees LLP  
101 West Broadway  
Suite 1600  
San Diego, CA 92101

1 future incur to investigate, remove or remediate hazardous substances, and alleged property  
 2 damage, including but not limited to alleged damage to aquatic life, at the Site.

3 **SECOND CAUSE OF ACTION**

4 **(Contribution Under CERCLA against all Defendants)**

5 129. Plaintiff realleges all prior paragraphs and incorporate them by reference.

6 130. Each Defendant is a "covered person" as defined by Section 107(a) of CERCLA,  
 7 42 U.S.C. § 9607(a). Each Defendant therefore is a "covered person," liable for contribution and  
 8 other relief to Plaintiff under 42 U.S.C. § 9613(f).

9 131. As responsible parties under section 9607(a) of CERCLA, Defendants, and each  
 10 of them, are liable to Plaintiff for contribution toward any costs it incurs in responding to and/or  
 11 reimbursing Plaintiff for the alleged release and/or threatened release of hazardous substances at  
 12 or into the Shipyard Sediment Site as alleged in herein, including without limitation, the costs of  
 13 investigation, clean-up, removal of contaminated sediments and soils, and completing any  
 14 additional investigation, monitoring, and remediation at the Shipyard Sediment Site, in amounts  
 15 to be determined at the trial of this matter.

16 132. Plaintiff requests that judgment be entered in its favor and against Defendants  
 17 pursuant to 42 U.S.C. § 9613 for contribution to the response costs that Plaintiff has incurred,  
 18 and will incur in the future, to investigate and/or remediate hazardous substances, and alleged  
 19 property damage, including but not limited to alleged damage to aquatic life, at the Site.

20 **THIRD CAUSE OF ACTION**

21 **(Declaratory Judgment Under CERCLA against all Defendants)**

22 133. Plaintiff realleges all prior paragraphs and incorporates them by reference.

23 134. CERCLA Section 113(g)(2), 42 U.S.C. § 9613(g)(2), provides that in an action to  
 24 recover costs, "the court shall enter a declaratory judgment on liability for response costs or  
 25 damages that will be binding on any subsequent action or actions to recover further response  
 26 costs or damages."

27 135. This action is an action of the type described in CERCLA Section 113(g)(2), 42  
 28 U.S.C. § 9613(g)(2).

Gordon & Rees LLP  
 101 West Broadway  
 Suite 1600  
 San Diego, CA 92101

1        136. An actual controversy has arisen and now exists among Plaintiff and Defendants  
2 in that Plaintiff contends, and Defendants deny, that Defendants are liable under CERCLA for  
3 the costs incurred and to be incurred by Plaintiff to investigate, remove or remediate hazardous  
4 substances at the Site.

5       137. Unless all of the rights, duties and obligations of Plaintiff and each Defendant are  
6 determined in this action, there will be a multiplicity of actions. Judicial determination of the  
7 liability of each party is necessary and appropriate in order that Plaintiff may ascertain its rights  
8 as against each Defendant.

9       138. Pursuant to 28 U.S.C. § 2201(a) and 42 U.S.C. § 9613(g)(2), this Court has  
10 jurisdiction to award declaratory relief. Plaintiff, therefore, request a judicial determination of its  
11 rights, and the duties and obligations of each Defendant, and all others, with respect to the  
12 alleged release and/or threatened release of hazardous substances at the Shipyard Sediment Site  
13 and the alleged property damage, including but not limited to alleged damage to aquatic life  
14 resulting therefrom. Plaintiff further requests that this Court apply all equitable factors and  
15 principles in determining the fault and liability of each party in making an allocation and  
16 apportionment for contributions by, between and among the parties.

## **FOURTH CAUSE OF ACTION**

**(Contribution Under Hazardous Substance Account Act against all Defendants)**

139. Plaintiff realleges all prior paragraphs and incorporates them by reference.

140. The California Hazardous Substance Account Act ("HSAA") codified at  
California Health & Safety Code §§ 25300 through 25395,45, states at § 25363(e):

22 Any person who has incurred removal or remedial action costs in accordance with this  
23 chapter or the federal act [defined as the Comprehensive Environmental Response,  
24 Compensation, and Liability Act of 1980, as amended (42 U.S.C. §§9601, et seq.)] may seek  
25 contribution or indemnity from any person who is liable pursuant to this chapter.

26        141. Plaintiff is a "person" who has incurred or will incur removal and remedial action  
27 costs in accordance with Chapter 6.8 of the HSAA and with the federal act, within the meaning  
28 of HSAA § 25319.

1           142. Each Defendant is a "person who is liable" for removal and remedial action costs  
 2 incurred by Plaintiff within the meaning of HSAA §§ 25319 and 25323.5.

3           143. The contaminants released or discharged by Defendants are "hazardous  
 4 substances" within the meaning of HSAA § 25316, and the federal act.

5           144. The Shipyard Sediment Site is a "site" within the meaning of HSAA § 25323.9.

6           145. The costs incurred by Plaintiff to investigate and remediate hazardous substances,  
 7 alleged property damage, and alleged injury at the Shipyard Sediment Site have been incurred  
 8 for "removal" or "remedial" actions within the meaning of HSAA §§ 25322 and 25323.

9           146. All removal and remedial costs incurred, and to be incurred, by Plaintiff at the  
 10 Shipyard Sediment Site are necessary costs of response that are consistent with HSAA §  
 11 25356.1.

12           147. Plaintiff has given or will give written notice of this action to the Regional Board  
 13 pursuant to HSAA § 25363(e).

14           148. Defendants are liable to Plaintiff for all removal and remedial costs incurred to  
 15 remedy the alleged effects of hazardous substances that Defendants have released or disposed at  
 16 the Site.

17           149. Plaintiff is entitled to contribution from Defendants for all response costs under  
 18 California Health & Safety Code Section 25363(e). Accordingly, Plaintiff requests that judgment  
 19 be entered in favor of Plaintiff and against Defendants as set forth below.

20           **FIFTH CAUSE OF ACTION**

21           **(Declaratory Relief Under California Hazardous Substance Account Act against all  
 22 Defendants)**

23           150. Plaintiff realleges all prior paragraphs and incorporates them by reference.

24           151. Plaintiff has incurred costs in connection with its investigation of contamination  
 25 at the Shipyard Sediment Site in accordance with the HSAA, California Health & Safety Code  
 26 §25300, et seq.

27           152. An actual controversy has arisen and now exists among Plaintiff and Defendants  
 28 in that Plaintiff contends, and Defendants deny, that Defendants are liable under the HSAA for

Gordon & Rees LLP  
 101 West Broadway  
 Suite 1600  
 San Diego, CA 92101

1 the costs incurred and to be incurred by Plaintiff to investigate, remove or remediate hazardous  
2 substances, and alleged property damage, including but not limited to alleged damage to aquatic  
3 life, at the Site.

4 153. Because the alleged contamination has not been fully mitigated according to  
5 regulatory agencies, Plaintiff will incur necessary response costs under the HSAA in the future.

6        154. Pursuant to California Health and Safety Code § 25363, Plaintiff is entitled to a  
7 declaratory judgment establishing Defendants' liability for such response costs for the purposes  
8 of this and any subsequent action or actions to recover further response costs. Accordingly,  
9 Plaintiff requests that judgment be entered in favor of Plaintiff and against Defendants as set  
10 forth below.

## **SIXTH CAUSE OF ACTION**

**(Contribution under State law against all Defendants except NAVY)**

155. Plaintiff incorporates the prior allegations by this reference as though fully set forth herein.

156. As a direct and proximate result of the releases and/or threatened releases of hazardous substances into the environment, as alleged above, Plaintiff has incurred and will incur response costs, beyond its share, for investigation and cleanup of the alleged contamination.

157. Plaintiff is informed and believes, and on that basis alleges, that the conduct of Defendants was the proximate cause of the damages which Plaintiff has incurred because of claims from third parties such as the Regional Board.

158. Under Section 1432 of the California Civil Code, which states that "a party to a joint, or joint and several obligation, who satisfies more than his share of the claim against all, may require a proportionate contribution from all the parties joined with him," and under general equitable principles and rules governing this action, Plaintiff is entitled to contribution from Defendants for their share of the response costs and damages paid and to be paid by Plaintiff.

## **SEVENTH CAUSE OF ACTION**

### **(Cost Recovery Pursuant to California Water Code)**

**Section 13304 against all Defendants)**

159. Plaintiff incorporates the prior allegations by this reference as though fully set forth herein.

- 6 160. California Water Code section 13304(a) states in relevant part:

Any person who has discharged or discharges waste into the waters of this state in violation of any waste discharge requirement or other order or prohibition issued by a regional board or state board, or who has caused or permitted, causes or permits, or threatens to cause or permit any waste to be discharged or deposited where it is, or probably will be, discharged into the waters of the state and creates, or threatens to create, a condition of pollution or nuisance, shall upon order of the regional board, clean up the waste, or, in the case of threatened pollution or nuisance, take other necessary remedial action, including, but not limited to, overseeing clean up and abatement efforts.

161. California Water Code section 13304(c)(1) states in relevant part:

If the waste is cleaned up or the effects of the waste are abated, or, in the case of threatened pollution or nuisance, other necessary remedial action is taken by any governmental agency, the person or persons who discharged the waste, discharges the waste, or threatened to cause or permit the discharge of the waste within the meaning of subdivision (a), are liable to that governmental agency to the extent of the reasonable costs actually incurred in cleaning up the waste, abating the effects of the waste, supervising cleanup or abatement activities, or taking other remedial action. The amount of the costs is recoverable in a civil action by, and paid to, the governmental agency . . .

162. Defendants, and each of them, through their operations at or adjacent to the  
Shipyard Sediment Site, discharged waste into the waters of the State in violation of their  
NPDES permits and the San Diego Basin Plan. The discharges of waste by Defendants have  
caused a condition of pollution and nuisance.

- 24       163. The waste discharged by Defendants, and each of them, and the alleged damage  
25 therefrom, have been and/or will be cleaned up and abated by Plaintiff, a governmental agency.  
26 Plaintiff has incurred, and will continue to incur, reasonable costs to investigate, clean up and  
27 abate the Shipyard Sediment Site.

1       164. Pursuant to Water Code section 13304(c)(1), Defendants, and each of them, are  
2 liable to Plaintiff for the costs it has and will incur in investigating, cleaning up and abating the  
3 waste discharged into the Shipyard Sediment Site by Defendants.

## **EIGHTH CAUSE OF ACTION**

### **(Breach of Contract/Breach of Lease)**

**6 (against NASSCO, NATIONAL STEEL & SHIPBUILDING CORPORATION & SDMCC  
DEFENDANTS)**

8 165. Plaintiff incorporates the prior allegations by this reference as though fully set  
forth herein.

166. Plaintiff is informed and believes and, upon such information and belief, alleges  
10 that Defendants NASSCO, NATIONAL STEEL & SHIPBUILDING CORPORATION and the  
11 SDMCC DEFENDANTS entered into contracts and leases with Plaintiff to lease the land on  
12 which they conducted business operations on or in the vicinity of the Shipyard Sediment Site.  
13 Said leases were entered into pursuant to Plaintiff's role as the designated public trustee for the  
14 tidelands area prior to Plaintiff transferring that authority to Defendant PORT DISTRICT in or  
15 about February 1963.

167. NASSCO and/or its predecessors leased the NAASCO Leasehold from Plaintiff  
for its operations from on or about 1945 to 1962.

16. NATIONAL STEEL & SHIPBUILDING CORPORATION leased land within  
17.  
18. the NASSCO Leasehold from Plaintiff for its operations from on or about 1950 to 1960.

169. The SDMCC DEFENDANTS leased land within the BAE Leasehold from  
Plaintiff for its operations from on or about 1915 to 1962.

22 Plaintiff was a non-operating trustee as to each parcel of property leased to these  
23 Defendants. Plaintiff did not conduct any operations on these parcels of property at any time;  
24 Plaintiff did not discharge any hazardous substances from these leaseholds; nor did Plaintiff  
25 cause or permit any hazardous substances to be discharged from these leaseholds. All operations  
26 on the parcels of property leased to these Defendants were conducted by Defendants.

1       171. In its leases with Plaintiff, NASSCO agreed to provide proper containers for trash  
2 and garbage and keep the demised premises free and clear of rubbish, debris and litter at all time,  
3 and, upon the expiration of the lease, to leave the premises in as good a condition as when first  
4 occupied by it. Defendant NASSCO further agreed to be responsible for all repairs and  
5 alterations upon the leased premises.

6       172. In its leases with Plaintiff, NATIONAL STEEL & SHIPBUILDING  
7 CORPORATION agreed to provide proper containers for trash and garbage and keep the  
8 demised premises free and clear of rubbish, debris and litter at all time, and, upon the expiration  
9 of the lease, to leave the premises in as good a condition as when first occupied by it. Defendant  
10 NATIONAL STEEL & SHIPBUILDING CORPORATION further agreed to be responsible for  
11 all repairs and alterations upon the leased premises.

12       173. In its leases with Plaintiff, the SDMCC DEFENDANTS agreed to do no work  
13 upon the premises that would materially decrease the amount of tidal waters in the San Diego  
14 Bay and to be responsible for all work or "change" upon the leased premises.

15       174. Plaintiff performed all of its obligations in these leases.

16       175. Defendants NASSCO and NATIONAL STEEL & SHIPBUILDING  
17 CORPORATION, and the SDMCC DEFENDANTS, have not performed their contractual  
18 obligations and duties expressly identified in their contracts with Plaintiff, as discussed above,  
19 given their respective releases of hazardous substances into the Shipyard Sediment Site during  
20 their historic operations thereat or in the vicinity thereof.

21       176. As a direct and proximate result of the breach of these contractual duties by these  
22 Defendants, Plaintiff has sustained damages in a sum presently unascertained, but in an amount  
23 to be shown according to proof at trial.

24       177. Plaintiff is informed and believes, and on such basis alleges, that these damages  
25 include, but are not limited to, costs incurred by Plaintiff to respond to the claims of regulatory  
26 agencies, including the Regional Board, and to investigate environmental contamination at the  
27 Shipyard Sediment Site, including at and about the parcels of property previously leased by  
28 Defendants from Plaintiff. Plaintiff is continuing to be damaged, and will have to spend

Gordon & Rees LLP  
101 West Broadway  
Suite 1600  
San Diego, CA 92101

1 additional sums for further investigation and remedial activity.

2       178. Plaintiff is informed and believes, and on such basis alleges that Plaintiff's  
3 damages are directly and proximately caused and contributed to by the sole fault and/or  
4 negligence and/or strict liability or other actionable conduct of Defendants via their operations at  
5 the parcels of property leased from Plaintiff.

6 179. Plaintiff prays for judgment as hereinafter set forth.

## **NINTH CAUSE OF ACTION**

**(Express Indemnity Against NASSCO, NATIONAL STEEL & SHIPBUILDING  
CORPORATION and SDMCC DEFENDANTS)**

9           180. Plaintiff incorporates the prior allegations by this reference as though fully set  
10 forth herein.

11           181. Defendants NASSCO, NATIONAL STEEL & SHIPBUILDING  
12 CORPORATION and the SDMCC DEFENDANTS entered into written contracts and leases  
13 with Plaintiff for the lease of property held in public trust by Plaintiff, as discussed above.

14 Plaintiff's lease agreements with NASSCO contain indemnity provisions, which  
15 require NASSCO to indemnify Plaintiff for costs incurred, or to be incurred, for cleaning up  
16 alleged environmental contamination at the Shipyard Sediment Site from its activities thereat.  
17 Defendant NASSCO expressly agreed to "save Lessor free and harmless and indemnify it against  
18 all claims for labor or materials for or in connection with any and all work, change or  
19 improvements in or upon the leased premises, and the costs of defending such claims, including  
20 reasonable attorney fees." Defendant NASSCO also agreed to take out public liability insurance  
21 to "protect against liability imposed by law or damages to any property or person caused directly  
22 or indirectly by or from the acts or activities of the Lessee or any person acting for it or under its  
23 control or direction...."

183. Plaintiff's lease agreements with NATIONAL STEEL & SHIPBUILDING  
CORPORATION contain indemnity provisions, which require NATIONAL STEEL &  
SHIPBUILDING CORPORATION to indemnify Plaintiff for costs incurred, or to be incurred,  
for cleaning up alleged environmental contamination at the Shipyard Sediment Site from its

1 activities there. Defendant NATIONAL STEEL & SHIPBUILDING CORPORATION  
 2 expressly agreed to "save Lessor free and harmless and indemnify it against all claims for labor  
 3 or materials for or in connection with any and all work, change or improvements in or upon the  
 4 leased premises, and the costs of defending such claims, including attorney fees." Defendant  
 5 NATIONAL STEEL & SHIPBUILDING CORPORATION also agreed to take out public  
 6 liability insurance to "protect against liability imposed by law or damages to any property or  
 7 person caused directly or indirectly by or from the acts or activities of the Lessee or any person  
 8 acting for it or under its control or direction...."

9       184. Plaintiff's lease agreements with the SDMCC DEFENDANTS contain indemnity  
 10 provisions, which require the SDMCC DEFENDANTS to indemnify Plaintiff for costs incurred,  
 11 or to be incurred, for removing and abating the alleged environmental contamination at the  
 12 Shipyard Sediment Site from its activities there. The SDMCC DEFENDANTS expressly agreed  
 13 to "save Lessor free and harmless and indemnify it against all claims for labor and materials in  
 14 connection with improvements, repairs and alterations in or upon the leased premises."

15       185. Plaintiff has performed and satisfied all the conditions precedent to the  
 16 obligations of the Leases.

17       186. None of the above-named Defendants have, to date, indemnified or held Plaintiff  
 18 free and harmless from the alleged property damage and alleged injury at issue resulting from  
 19 their acts, omissions and operations at or near the Site, and their changes and alterations to the  
 20 property leased from Plaintiff, as agreed in their Leases with Plaintiff. Nor have any of the  
 21 above-named Defendants, to date, acknowledged a duty to do so.

22       187. Plaintiff is informed and believes and, upon such information and belief, alleges  
 23 that Plaintiff's damages are directly and proximately caused and contributed to by the sole fault,  
 24 and/or negligence, and/or strict liability and/or other actionable conduct of Defendants in their  
 25 operations at or in the vicinity of the Shipyard Sediment Site.

26       188. Plaintiff is entitled to indemnity from Defendants as expressly provided by  
 27 contract for all costs incurred, and to be incurred, by Plaintiff in connection with the  
 28 contamination at the Shipyard Sediment Site, including attorneys' fees where provided for by

Gordon & Rees LLP  
 101 West Broadway  
 Suite 1600  
 San Diego, CA 92101

1 contract.

2 **TENTH CAUSE OF ACTION**

3 **(Negligence against all Defendants except NAVY)**

4 189. Plaintiff realleges and incorporates the prior allegations by this reference as  
5 though fully set forth herein.

6 190. Defendants had a duty of care with respect to their operations and actions at or  
7 near the Shipyard Sediment Site and/or their ownership of and management of and authority over  
8 property on which defendants operated and acted.

9 191. Plaintiff is informed and believes, and on that basis alleges, that Defendants, and  
10 each of them, breached their duty of care in connection with their operation of or activities at or  
11 near the Shipyard Sediment Site by virtue of their actions as alleged herein.

12 192. These breaches of duty by Defendants proximately caused the accidental releases  
13 and/or threatened releases of hazardous substances at the Shipyard Sediment Site. Plaintiff has  
14 incurred costs in responding to those releases and expects to incur additional costs in the future  
15 as a result of this negligence on the part of Defendants.

16 193. Consequently, Plaintiff is entitled to damages according to proof at trial.

17 **ELEVENTH CAUSE OF ACTION**

18 **(Negligence Per Se against all Defendants except NAVY))**

19 194. Plaintiff realleges and incorporates the prior allegations by this reference as  
20 though fully set forth herein.

21 195. Plaintiff is informed and believes, and on that basis alleges, that Defendants'  
22 conduct, as detailed herein, leading to the release and/or threatened accidental releases of  
23 hazardous substances at the Site violated applicable legal requirements governing the transport,  
24 handling, storage, treatment, use and disposal of hazardous substances. Such releases or  
25 threatened releases are the type of occurrences which the aforementioned legal requirements are  
26 designed to prevent.

27 196. Plaintiff is informed and believes, and on that basis alleges, that Defendants had  
28 knowledge or reasonable cause to believe that releases and/or threatened releases of hazardous

1 substances by Defendants have come or will come to be located on or about the Shipyard  
2 Sediment Site in amounts required to be reported to a state or local agency pursuant to law, and  
3 Defendants did not give Plaintiff timely and adequate written notice, if any, of the releases or  
4 threatened releases or of that condition to Plaintiff.

5 197. Plaintiff is among the class of persons which such legal requirements were  
6 designed and intended to protect.

7 198. The violations by Defendants of those legal requirements proximately caused  
8 harm to Plaintiff, who has been required to respond to said releases and/or threatened releases of  
9 hazardous substances at the Shipyard Sediment Site, and who will be required to continue to  
10 respond to them in the foreseeable future. As a result of Defendants' actions, Plaintiff is entitled  
11 to damages according to proof at trial.

12 199. The foregoing acts and omissions of Defendants, as detailed in the general  
13 allegations herein, violate various statutory provisions, including but not limited to, California  
14 Health and Safety Code §§ 25359, et. seq.; California Health and Safety Code §§ 25249.5 et  
15 seq.; California Health and Safety Code §§ 25100 et seq.; Health & Safety Code §§ 25189(c)-  
16 (d); California Water Code §§ 13000 et. seq. (including § 13400); and Fish & Game Code §§  
17 5650, et. seq.

18 200. Defendants failed to comply with the state law as detailed above. Plaintiff has  
19 sustained injury as a result of Defendants' negligent conduct, including investigative costs,  
20 removal and remedial costs, attorney's fees and expert costs, and other costs, as described herein.  
21 As a further direct and proximate cause of the negligence per se by Defendants, Plaintiff has  
22 suffered damages as previously described herein, including other consequential, incidental, and  
23 general damages to be proven at trial.

24 201. As a result of Defendants' statutory violations, Plaintiff prays for damages and  
25 any other relief appropriate under the law as set forth below.

26 **TWELFTH CAUSE OF ACTION**

27 **(Private Nuisance against all Defendants except NAVY)**

28 202. Plaintiff realleges and incorporates the prior allegations by this reference as

1 though fully set forth herein.

2 203. Plaintiff is informed and believes, and on that basis alleges, that Defendants  
3 released and/or discharged hazardous substances into the Shipyard Sediment Site in violation of  
4 the law and public and private safety by improperly releasing, discharging, handling, and  
5 disposing of hazardous substances, resulting in contamination of the Site, as discussed in detail  
6 herein.

7       204. Plaintiff is informed and believes, and on that basis alleges, that the contamination  
8 at the Site constitutes a nuisance under California Civil Code sections 3479 and 3481, because it  
9 is injurious to health and interferes with the customary use of the Shipyard Sediment Site and  
10 surrounding area.

11        205. Plaintiff has sustained injury as a result of this nuisance, including investigative  
12 costs, removal and remedial costs, attorney's fees and expert costs, and other costs, as described  
13 herein. Plaintiff has and will continue to suffer economic damages as previously described  
14 herein, including other consequential, incidental, and general damages in an amount to be proven  
15 at trial for investigating and responding to this nuisance.

## **THIRTEENTH CAUSE OF ACTION**

**(Public Nuisance against all Defendants except NAVY)**

18 206. Plaintiff realleges and incorporates the prior allegations by this reference as  
19 though fully set forth herein.

20        207. Defendants' discharge, deposit, disposal and release of hazardous substances at  
21 the Shipyard Sediment Site has resulted in conditions that are injurious to health, offensive to the  
22 senses, and an interference with the free use of property so as to interfere with the comfortable  
23 enjoyment of life and property. The conditions caused by Defendants constitute a nuisance  
24 within the meaning of California Civil Code § 3479.

25        208. The nuisance caused by Defendants is a public nuisance because it affects an  
26 entire area or neighborhood and a considerable number of persons within the meaning of  
27 California Civil Code § 3480.

209. Plaintiff has standing to bring this action to abate the public nuisance because it

1 has been specially injurious to Plaintiff within the meaning of California Civil Code § 3495.

2 210. The public nuisance is continuing because, among other things, it can be abated  
3 and it varies over time.

4 211. As a direct and proximate result of the public nuisance caused by Defendants,  
5 Plaintiff has been damaged as alleged herein. In accordance with California Code of Civil  
6 Procedure § 731, Plaintiff is entitled to damages as well as injunctive relief requiring Defendants  
7 to abate the continuing public nuisance.

8 212. As a result of the public nuisance, Plaintiff prays for injunctive relief and damages  
9 as set forth below.

10 **FOURTEENTH CAUSE OF ACTION**

11 **(Trespass against all Defendants except NAVY)**

12 213. Plaintiff realleges and incorporates the prior allegations by this reference as  
13 though fully set forth herein.

14 214. From on or about 1914 to 1962, Plaintiff served as the trustee of the NASSCO  
15 and BAE SYSTEMS' leaseholds on behalf of the People of the State of California. Furthermore,  
16 from on or about 1914 to present, Plaintiff has been in lawful possession of its MS4 storm water  
17 system which is located at and about the Shipyard Sediment Site, including its SW4 outfall at the  
18 BAE SYSTEMS leasehold.

19 215. Defendants caused hazardous substances to intrude on the above-described  
20 property that was lawfully in the possession of Plaintiff. Such intrusion was not permitted.

21 216. Plaintiff is informed and believes, and on that basis alleges, that this intrusion was  
22 intentional or negligent or resulted from ultra hazardous conduct.

23 217. Defendants' trespass directly and proximately caused damages that have been,  
24 and will continue to be, sustained by Plaintiff.

25 218. Consequently, Plaintiff is entitled to damages according to proof at trial.

26 **FIFTEENTH CAUSE OF ACTION**

27 **(Declaratory Relief Under State Law against all Defendants except NAVY)**

28 219. Plaintiff realleges and incorporates the prior allegations by this reference as

Gordon & Rees LLP  
101 West Broadway  
Suite 1600  
San Diego, CA 92101

1 though fully set forth herein.

2 220. An actual controversy exists between Plaintiff and Defendants with respect to  
3 their respective rights and obligations under federal and state laws. Plaintiff seeks a judicial  
4 determination of the respective rights and duties of the parties with respect to the rights, claims  
5 and damages alleged herein.

6 221. Plaintiff also seeks a declaration by this court that Defendant NASSCO and the  
7 SDMCC DEFENDANTS are obligated contractually to investigate and clean up the  
8 contamination at issue, and to indemnify and hold Plaintiff harmless; that Plaintiff complied with  
9 all conditions and obligations under the leases at issue; and that because of Defendants' breach  
10 of lease, negligence, nuisance, trespass, and statutory violations, Plaintiff has been damaged  
11 according to proof.

12 222. The requested declaration is necessary and appropriate at this time to allow  
13 Plaintiff to ascertain its rights and duties with respect to the claims at issue in this action.

14 223. As a result, Plaintiff prays for declaratory relief as set forth below.

15 **PRAYER FOR RELIEF**

16 Plaintiff prays for judgment against Defendants as follows:

17 1. For recovery of costs from Defendants for costs which Plaintiff has incurred and  
18 expects to incur in responding to releases of hazardous substances at the Shipyard Sediment Site  
19 including without limitation, the costs of investigation, clean-up, removal of contaminated soils,  
20 and completing any additional investigation, monitoring, and remediation at the Shipyard  
21 Sediment Site, in amounts to be determined at the trial of this matter;

22 2. For contribution toward any costs which Plaintiff has incurred or will incur in  
23 responding to the releases of hazardous substances at the Shipyard Sediment Site as alleged in  
24 Plaintiffs' complaint, including without limitation, the costs of investigation, clean-up, dredging  
25 of contaminated sediments, and completing any additional investigation, monitoring, and  
26 remediation at the Shipyard Sediment Site, in amounts to be determined at the trial of this matter;

27 2. For indemnification and/or contribution in full or in part to any costs, damages  
28 and liabilities arising from the alleged contamination of the Shipyard Sediment Site which

Gordon & Rees LLP  
101 West Broadway  
Suite 1600  
San Diego, CA 92101

1 Plaintiff incurs in responding to the releases and/or threatened releases of hazardous substances  
2 at the Shipyard Sediment Site including without limitation, the costs of investigation, clean-up,  
3 dredging of contaminated sediments, monitoring, and completing any additional investigation  
4 and remediation at the Property, in amounts to be determined at the trial of this matter;

5       3. For a declaration determining of the rights of Plaintiff, and the duties and  
6 obligations of each Defendant, and all others, with respect to the releases and/or threatened  
7 releases of hazardous substances at and into the Shipyard Sediment Site and the alleged damages  
8 resulting therefrom;

9       4. For a declaration that Defendant NASSCO and the SDMCC DEFENDANTS are  
10 obligated to indemnify and hold Plaintiff harmless from and against any and all claims arising  
11 out of their alleged contamination at or into the Shipyard Sediment Site;

12       5. For an order directing Defendants to cease any ongoing unlawful releases and/or  
13 threatened releases of hazardous substances at the Shipyard Sediment Site;

14       6. For damages according to proof at trial, including but not limited to all costs and  
15 expenses paid and to be paid in complying with the Regional Board's claims relating to  
16 investigation and cleanup of the Site;

17       7. For an award of the costs of this litigation including but not limited to costs that  
18 Plaintiff has incurred and will continue to incur to defend against claims relating to the  
19 investigation and cleanup of alleged contamination on the Site, reasonable attorneys' fees and  
20 experts' fees;

21       8. For any and all remedies authorized under section California Health and Safety  
22 Code §§ 25359, et. seq.; California Health and Safety Code §§ 25249.5 et seq.; California Health  
23 and Safety Code §§ 25100 et seq.; Health & Safety Code §§ 25189(c)(d); California Water Code  
24 §§ 13000 et. seq.; and Fish & Game Code §§ 5650, et. seq.;

25       9. For prejudgment interest at the maximum rate permitted by law;

26       10. For such other and further relief as the Court may deem appropriate.

Gordon & Rees LLP  
101 West Broadway  
Suite 1600  
San Diego, CA 92101

## JURY DEMAND

Plaintiff hereby demands a trial by jury of all issues triable by jury.

Dated: October 13, 2009

GORDON & REES, LLP

By:   
Brian M. Ledger  
Kristin N. Reyna  
Attorneys for City of San Diego

Gordon & Rees LLP  
101 West Broadway  
Suite 1600  
San Diego, CA 92101

## **EXHIBIT “A”**

## **TENTATIVE**

### **CALIFORNIA REGIONAL WATER QUALITY CONTROL BOARD SAN DIEGO REGION**

#### **TENTATIVE CLEANUP AND ABATEMENT ORDER NO. R9-2005-0126**

**NATIONAL STEEL AND SHIPBUILDING COMPANY**

**BAE SYSTEMS SAN DIEGO SHIP REPAIR, INC.  
(FORMERLY SOUTHWEST MARINE, INC.)**

**CITY OF SAN DIEGO**

**MARINE CONSTRUCTION AND DESIGN COMPANY  
AND CAMPBELL INDUSTRIES, INC.**

**SAN DIEGO GAS AND ELECTRIC,  
A SUBSIDIARY OF SEMPRA ENERGY COMPANY**

**UNITED STATES NAVY**

**SHIPYARD SEDIMENT SITE  
SAN DIEGO BAY  
SAN DIEGO, CALIFORNIA**

The California Regional Water Quality Control Board, San Diego Region (hereinafter Regional Board), finds that:

#### ***JURISDICTION***

- 1. WASTE DISCHARGE.** Elevated levels of pollutants above San Diego Bay background conditions exist in the San Diego Bay bottom marine sediment along the eastern shore of central San Diego Bay in an area extending approximately from the Sampson Street Extension to the north and Chollas Creek to the south and from the National Steel and Shipbuilding Company Shipyard facility (hereinafter "NASSCO") and the BAE Systems San Diego Ship Repair Facility (hereinafter "BAE Systems") shoreline out to the San Diego Bay

Revised Tentative Cleanup and Abatement Order No. R9-2005-0126  
Shipyard Sediment Site

April 4, 2008

main shipping channel to the west. This area is hereinafter collectively referred to as the "Shipyard Sediment Site". NASSCO; BAE Systems San Diego Ship Repair, Inc.; City of San Diego; Marine Construction and Design Company and Campbell Industries, Inc.; San Diego Gas and Electric, a subsidiary of Sempra Energy Company; and the United States Navy have each caused or permitted the discharge of waste to the Shipyard Sediment Site resulting in the accumulation of waste in the marine sediment. The contaminated marine sediment has caused conditions of contamination or nuisance in San Diego Bay that adversely affects aquatic life, aquatic-dependent wildlife, human health, and San Diego Bay beneficial uses. A map of the Shipyard Sediment Site region is provided in Attachment 1 to this Order.

*PERSONS RESPONSIBLE*

2. **NATIONAL STEEL AND SHIPBUILDING COMPANY (NASSCO), A SUBSIDIARY OF GENERAL DYNAMICS COMPANY.** The National Steel and Shipbuilding Company, (hereinafter NASSCO) has (1) discharged waste from its shipyard operations into San Diego Bay in violation of waste discharge requirements; and (2) caused or permitted waste to be discharged or deposited where it was discharged into San Diego Bay and created, or threatens to create, a condition of pollution or nuisance. These wastes contained metals (arsenic, cadmium, chromium, copper, lead, mercury, nickel, silver, and zinc), butyl tin species, polychlorinated biphenyls (PCBs), polychlorinated terphenyls (PCTs), polynuclear aromatic hydrocarbons (PAHs), and total petroleum hydrocarbons (TPH). Based on these considerations NASSCO is referred to as "Discharger(s)" in this Cleanup and Abatement Order.

NASSCO, a subsidiary of General Dynamics Company, owns and operates a full service ship construction, modification, repair, and maintenance facility on 126 acres of tidelands property leased from the San Diego Unified Port District (SDUPD) on the eastern waterfront of central San Diego Bay at 2798 Harbor Drive in San Diego. Shipyard operations have been conducted at this site by NASSCO over San Diego Bay waters or very close to the waterfront since 1945. Shipyard facilities operated by NASSCO over the years at the Site have included concrete platens used for steel fabrication, a graving dock, shipbuilding ways, and berths on piers or land to accommodate the berthing of ships. An assortment of waste is generated at the facility including spent abrasive, paint, rust, petroleum products, marine growth, sanitary waste, and general refuse.

Revised Tentative Cleanup and Abatement Order No. R9-2005-0126  
Shipyard Sediment Site

April 4, 2008

- 3. BAE SYSTEMS SAN DIEGO SHIP REPAIR, INC., FORMERLY SOUTHWEST MARINE, INC.** BAE Systems San Diego Ship Repair, Inc. has (1) discharged waste from its shipyard operations into San Diego Bay in violation of waste discharge requirements; and (2) caused or permitted waste to be discharged or deposited where it was discharged into San Diego Bay and created, or threatens to create, a condition of pollution or nuisance. These wastes contained metals (arsenic, cadmium, chromium, copper, lead, mercury, nickel, silver, and zinc), butyl tin species, polychlorinated biphenyls (PCBs), polychlorinated terphenyls (PCTs), polynuclear aromatic hydrocarbons (PAHs), and total petroleum hydrocarbons (TPH). Based on these considerations BAE Systems San Diego Ship Repair, Inc. is referred to as "Discharger(s)" in this Cleanup and Abatement Order.

From 1979 to the present, Southwest Marine, Inc. and its successor BAE Systems San Diego Ship Repair, Inc., hereinafter collectively referred to as BAE Systems, have owned and operated a ship repair, alteration, and overhaul facility on approximately 39.6 acres of tidelands property on the eastern waterfront of central San Diego Bay. The facility, currently referred to as BAE Systems San Diego Ship Repair, is located on land leased from the San Diego Unified Port District (SDUPD) at 2205 East Belt Street, foot of Sampson Street in San Diego, San Diego County, California. Shipyard facilities operated by BAE Systems over the years have included concrete platens used for steel fabrication, two floating dry docks, five piers, and two marine railways. An assortment of waste has been generated at the facility including spent abrasive, paint, rust, petroleum products, marine growth, sanitary waste, and general refuse.

- 4. CITY OF SAN DIEGO.** The City of San Diego owns and operates a municipal separate storm sewer system (MS4) through which it discharges waste commonly found in urban runoff to San Diego Bay subject to the terms and conditions of a NPDES Storm Water Permit. The City of San Diego has discharged urban storm water containing waste directly to San Diego Bay at the Shipyard Sediment Site in violation of waste discharge requirements. The waste includes metals (arsenic, cadmium, chromium, copper, lead, mercury, nickel, silver, and zinc), total suspended solids, sediment (due to anthropogenic activities), petroleum products, and synthetic organics (pesticides, herbicides, and PCBs) through its SW4 (located on the BAE Systems leasehold) and SW9 (located on the NASSCO leasehold) MS4 conduit pipes.

The City of San Diego has also discharged urban storm water containing waste in violation of waste discharge requirements, through its MS4 to Chollas Creek resulting in the exceedances of chronic and acute California Toxics Rule copper, lead, and zinc criteria for the protection of aquatic life, in violation of waste discharge requirements prescribed by the Regional Board. Studies indicate that during storm events, storm water plumes toxic to marine life emanate from Chollas Creek up to 1.2 kilometers into San Diego Bay, and contribute to pollutant levels at the Shipyard Sediment Site. The urban storm water containing waste that has discharged from the on-site and off-site MS4 has contributed to the accumulation of pollutants in the marine sediments at the Shipyard Sediment Site to levels, that cause, and threaten to cause, conditions of pollution, contamination, and nuisance by exceeding applicable water quality objectives for toxic pollutants in San Diego Bay. Based

Revised Tentative Cleanup and Abatement Order No. R9-2005-0126  
Shipyard Sediment Site

April 4, 2008

on these considerations the City of San Diego is referred to as "Discharger(s)" in this Cleanup and Abatement Order.

- 5. MARINE CONSTRUCTION AND DESIGN COMPANY AND CAMPBELL INDUSTRIES, INC.** Marine Construction and Design Company and Campbell Industries, Inc. (hereinafter collectively referred to as "SDMC") has (1) discharged pollutants from its shipyard operations into San Diego Bay in violation of waste discharge requirements; and (2) caused or permitted waste to be discharged or deposited where it was discharged into San Diego Bay and created, or threatens to create, a condition of pollution or nuisance. These wastes contained metals (arsenic, cadmium, chromium, copper, lead, mercury, nickel, silver, and zinc), butyl tin species, polychlorinated biphenyls (PCBs), polychlorinated terphenyls (PCTs), polynuclear aromatic hydrocarbons (PAHs), and total petroleum hydrocarbons (TPH). Based on these considerations, Marine Construction and Design Company and Campbell Industries, Inc. are referred to as "Discharger(s)" in this Cleanup and Abatement Order.

Between 1914 and 1979, San Diego Marine Construction Company and its successor San Diego Marine Construction Corporation, a wholly owned subsidiary of Campbell Industries, Inc., a wholly owned subsidiary of Marine Construction and Design Company (MARCO), collectively referred to as SDMC, operated a ship repair, alteration, and overhaul facility on what is now the BAE Systems leasehold at the foot of Sampson Street in San Diego. Shipyard operations were conducted at this site by SDMC over San Diego Bay waters or very close to the waterfront. An assortment of waste was generated at the facility including spent abrasive blast waste, paint, rust, petroleum products, marine growth, sanitary waste, and general refuse.

- 6. CHEVRON, A SUBSIDIARY OF CHEVRONTEXACO.** Chevron owns and operates the Chevron Terminal, a bulk fuel storage facility currently located at 2351 East Harbor Drive in the City of San Diego adjacent to the NASSCO and BAE Systems leaseholds. Fuel products containing petroleum hydrocarbons have been stored at the Chevron Terminal since the early 1900s at both the currently operating 7 million gallon product capacity upper tank farm and the closed 5 million gallon capacity lower tank farm. Based on the information that the Regional Board has reviewed to date, there is insufficient evidence to find that discharges from the Chevron Terminal contributed to the accumulation of pollutants in the marine sediments at the Shipyard Sediment Site to levels, which create, or threaten to create, conditions of pollution or nuisance. Accordingly, Chevron is not referred to as "Discharger(s)" in this Cleanup and Abatement Order.

Revised Tentative Cleanup and Abatement Order No. R9-2005-0126  
Shipyard Sediment Site

April 4, 2008

**7. BP AS THE PARENT COMPANY AND SUCCESSOR TO ATLANTIC RICHFIELD.**

BP owns and operates the Atlantic Richfield Company (ARCO) Terminal, a bulk fuel storage facility with approximately 9 million gallons of capacity located at 2295 East Harbor Drive in the City of San Diego. Fuel products containing petroleum hydrocarbons and related constituents such as polynuclear aromatic hydrocarbons (PAHs) have been stored at ARCO Terminal since the early 1900s. ARCO owned and operated ancillary facilities include a wharf, fuel pier (currently BAE Systems Pier 4), and a marine fueling station used for loading and unloading petroleum products and fueling from 1925 to 1978, and five pipelines connecting the terminal to the pier and wharf in use from 1925 to 1978. Storm water flows from ARCO Terminal enter a City of San Diego MS4 storm drain that terminates in San Diego Bay in the Shipyard Sediment Site approximately 300 feet south of the Sampson Street extension. Based on the information that the Regional Board has reviewed to date, there is insufficient evidence to find that discharges from the ARCO Terminal contributed to the accumulation of pollutants in the marine sediments at the Shipyard Sediment Site to levels, which create, or threaten to create, conditions of pollution or nuisance. Accordingly, BP and ARCO are not referred to as "Discharger(s)" in this Cleanup and Abatement Order.

**8. SAN DIEGO GAS AND ELECTRIC, A SUBSIDIARY OF SEMPRA ENERGY.**

SDG&E (1) has discharged waste from its power plant operations, including metals (copper, nickel, and zinc) into San Diego Bay in violation of waste discharge requirements; and (2) caused or permitted waste (including metals [chromium, copper, lead, nickel, and zinc], polychlorinated biphenyls [PCBs], polynuclear aromatic hydrocarbons [PAHs], and total petroleum hydrocarbons [TPH-d and TPH-h]) to be discharged or deposited where it was discharged into San Diego Bay and created, or threatens to create, a condition of pollution or nuisance. Based on these considerations SDG&E is referred to as "Discharger(s)" in this Cleanup and Abatement Order.

San Diego Gas and Electric, a subsidiary of Sempra Energy Company (hereinafter SDG&E) owned and operated the Silver Gate Power Plant along the north side of the BAE Systems leasehold from approximately 1943 to the 1990s. SDG&E utilized an easement to San Diego Bay along BAE Systems' north property boundary for the intake and discharge of cooling water via concrete tunnels at flow rates ranging from 120 to 180 million gallons per day. SDG&E operations included discharging waste to holding ponds above the tunnels near the Shipyard Sediment Sites.

Revised Tentative Cleanup and Abatement Order No. R9-2005-0126  
Shipyard Sediment Site

April 4, 2008

**9. UNITED STATES NAVY.** The U.S. Navy owns and operates a municipal separate storm sewer system (MS4) at NAVSTA San Diego through which it has caused or permitted the discharge of waste commonly found in urban runoff to Chollas Creek and San Diego Bay, including excessive concentrations of copper, lead, and zinc in violation of waste discharge requirements. Technical reports by the U.S. Navy and others indicate that Chollas Creek outflows during storm events convey elevated sediment and urban runoff chemical pollutant loading and its associated toxicity up to 1.2 kilometers into San Diego Bay over an area including the Shipyard Sediment Site. The U.S. Navy has caused or permitted marine sediment and associated waste to be resuspended into the water column as a result of shear forces generated by the thrust of propellers during ship movements at NAVSTA San Diego. The resuspended sediment and pollutants can be transported by tidal currents and deposited in other parts of San Diego Bay, including the Shipyard Sediment Site. The above discharges have contributed to the accumulation of pollutants in marine sediment at the Shipyard Sediment Site to levels that cause, and threaten to cause, conditions of pollution, contamination, and nuisance by exceeding applicable water quality objectives for toxic pollutants in San Diego Bay. Based on the preceding considerations, the U.S. Navy is referred to as "Discharger(s)" in this Cleanup and Abatement Order.

From the year 1921 to the present, the U.S. Navy has provided shore support and pier-side berthing services to U.S. Pacific fleet vessels at Naval Station San Diego (NAVSTA San Diego) located at 3445 Surface Navy Boulevard in the City of San Diego. NAVSTA San Diego currently occupies 1,029 acres of land and 326 water acres adjacent to San Diego Bay to the west, and Chollas Creek to the north near Pier 1. Between the years 1938 and 1956 the NAVSTA San Diego leasehold included a parcel of land, referred to as the 28<sup>th</sup> Street Shore Boat Landing Station, located at the south end of the present day NASSCO leasehold at the foot of 28<sup>th</sup> Street and including the 28<sup>th</sup> Street Pier. At this location, the U.S. Navy conducted operations similar in scope to a small boatyard including solvent cleaning and degreasing of vessel parts and surfaces, abrasive blasting and scraping for paint removal and surface preparations, metal plating, and surface finishing and painting. Prevailing industry-wide boatyard operational practices employed during the 1930s through the 1980s were often not sufficient to adequately control or prevent pollutant discharges and often led to excessive discharges of pollutants and accumulation of pollutants in marine sediment in San Diego Bay. The types of pollutants found in elevated concentrations at the Shipyard Sediment Site (metals, butyltin species, polychlorinated biphenyls (PCBs), polychlorinated terphenyls (PCTs), polynuclear aromatic hydrocarbons (PAHs), and total petroleum hydrocarbons (TPH)) are associated with the characteristics of the waste the U.S. Navy operations generated at the 28<sup>th</sup> Street Shore Boat Landing Station site.

Revised Tentative Cleanup and Abatement Order No. R9-2005-0126  
Shipyard Sediment Site

April 4, 2008

#### *FACTUAL BACKGROUND*

- 10. CLEAN WATER ACT SECTION 303(d) LIST.** Approximately 55 acres of San Diego Bay shoreline between Sampson and 28<sup>th</sup> Streets is listed on the Clean Water Act Section 303(d) list of water quality limited segments for elevated levels of copper, mercury, zinc, PAHs, and PCBs in the marine sediment. These pollutants are impairing the aquatic life, aquatic-dependent wildlife, and human health beneficial uses designated for San Diego Bay. The Shipyard Sediment Site occupies this shoreline. The Regional Board has determined that issuance of a cleanup and abatement order (in lieu of a Total Maximum Daily Load program) is the appropriate regulatory tool to use for correcting the impairment at the Shipyard Sediment Site.
- 11. SEDIMENT QUALITY INVESTIGATION.** NASSCO and BAE Systems (formerly Southwest Marine) conducted a detailed sediment investigation at the Shipyard Sediment Site in San Diego Bay within and adjacent to the NASSCO and BAE Systems leaseholds. Two phases of fieldwork were conducted, Phase I in 2001 and Phase II in 2002. The results of the investigation are provided in the Exponent report *NASSCO and Southwest Marine Detailed Sediment Investigation, September 2003* (Shipyard Report). Unless otherwise explicitly stated, the Regional Board's finding and conclusions in this Cleanup and Abatement Order are based on the data and other technical information contained in the Shipyard Report prepared by NASSCO's and BAE Systems' consultant, Exponent.

#### *AQUATIC LIFE BENEFICIAL USE IMPAIRMENT*

- 12. AQUATIC LIFE IMPAIRMENT.** Aquatic life beneficial uses designated for San Diego Bay are impaired due to the elevated levels of pollutants present in the marine sediment at the Shipyard Sediment Site. Aquatic life beneficial uses include: Estuarine Habitat (EST), Marine Habitat (MAR), and Migration of Aquatic Organisms (MIGR). This finding is based on the considerations described below in this *Impairment of Aquatic Life Beneficial Uses* section of the Cleanup and Abatement Order.
- 13. WEIGHT-OF-EVIDENCE APPROACH.** The Regional Board used a weight-of-evidence approach based upon multiple lines of evidence to evaluate the potential risks to aquatic life beneficial uses from pollutants at the Shipyard Sediment Site. The approach focused on measuring and evaluating exposure and adverse effects to the benthic macroinvertebrate community and to fish using data from multiple lines of evidence and best professional judgment. Pollutant exposure and adverse effects to the benthic macroinvertebrate community were evaluated using sediment quality triad measurements, bioaccumulation analyses, and interstitial water (i.e., pore water) analyses. The Regional Board evaluated pollutant exposure and adverse effects to fish using fish histopathology analyses and analyses of PAH breakdown products in fish bile.

Revised Tentative Cleanup and Abatement Order No. R9-2005-0126  
Shipyard Sediment Site

April 4, 2008

**14. SEDIMENT QUALITY TRIAD MEASURES.** The Regional Board used lines of evidence organized into a sediment quality triad, to evaluate potential risks to the benthic community from pollutants present in the Shipyard Sediment Site. The sediment quality triad provides a "weight-of-evidence" approach to sediment quality assessment by integrating synoptic measures of sediment chemistry, toxicity, and benthic community composition. All three measures provide a framework of complementary evidence for assessing the degree of pollutant-induced degradation in the benthic community.

**15. REFERENCE SEDIMENT QUALITY CONDITIONS.** The Regional Board selected a group of reference stations from three independent sediment quality investigations to contrast pollution conditions at the Shipyard Sediment Site with conditions found in other relatively cleaner areas of San Diego Bay not affected by the Shipyard Sediment Site: (1) Southern California Bight 1998 Regional Monitoring Program (Bight '98), (2) 2001 Mouth of Chollas Creek and Mouth of Paleta Creek TMDL studies, and (3) 2001 NASSCO and Southwest Marine (now BAE Systems) Detailed Sediment Investigation. Stations from these studies were selected to represent selected physical, chemical, and biological characteristics of San Diego Bay. Criteria for selecting acceptable reference stations included low levels of anthropogenic pollutant concentrations, locations remote from pollution sources, similar biological habitat to the Shipyard Sediment Site, sediment total organic carbon (TOC) and grain size profiles similar to the Shipyard Sediment Site, adequate sample size for statistical analysis, and sediment quality data comparability. The reference stations selected for the Reference Sediment Quality Conditions are identified below.

#### Reference Stations Used To Establish Reference Sediment Quality Conditions

2001 Chollas/Paleta Reference Station Identification Number	2001 NASSCO/BAE Systems Reference Station Identification Number	1998 Bight '98 Reference Station Identification Number
2231	2231	2235
2243	2243	2241
2433	2433	2242
2441	2441	2243
2238		2256
		2257
		2258
		2260
		2265

Revised Tentative Cleanup and Abatement Order No. R9-2005-0126  
Shipyard Sediment Site

April 4, 2008

- 16. SEDIMENT QUALITY TRIAD RESULTS.** The Regional Board categorized 14 of 30 Sediment Quality Triad sampling stations at the Shipyard Sediment Site as having sediment pollutant levels "likely" to adversely affect the health of the benthic community. These results are based on the synoptic measures of sediment chemistry, toxicity, and benthic community structure at the Shipyard Sediment Site. In addition, an evaluation of 27 of the sampling stations utilizing the State Water Resources Control Board's Draft Sediment Quality Objectives categorizes 20 of 27 stations as not protective of aquatic life.
- 17. BIOACCUMULATION.** The Regional Board evaluated initial laboratory bioaccumulation test data to ascertain the bioaccumulation potential of the sediment chemical pollutants at the Shipyard Sediment Site. Examination of laboratory test data on the chemical pollutant concentrations in tissue of the clam (*Macoma nasuta*) relative to the pollutant concentrations in sediment indicates that bioaccumulation of chemical pollutants is occurring at the Shipyard Sediment Site. The data indicates for several chemical pollutants that concentrations in *Macoma nasuta* tissue increase in proportion to as chemical pollutant concentrations in sediment increase. Statistically significant relationships were found for arsenic, copper, lead, mercury, zinc, TBT, total PCBs, and high molecular weight polynuclear aromatic hydrocarbons (HPAHs). These chemical pollutants have a bioaccumulation potential at the Shipyard Sediment Site and are therefore considered bioavailable to benthic organisms. No statistically significant relationships were found for cadmium, chromium, nickel, selenium, silver, or PCTs.
- 18. PORE WATER.** The Regional Board evaluated the chemistry of pore water, the water occupying the spaces between sediment particles, at the Shipyard Sediment Site to determine compliance with California Toxics Rule (CTR) water quality criteria and the potential risks to the benthic community from chemical pollutants present in the sediment. Comparisons were made to the CTR saltwater quality criterion continuous concentration, which is the highest concentration of a pollutant to which marine aquatic life can be exposed for an extended period of time without deleterious effects. Of the 12 site stations sampled for pore water (SW02 was excluded due to the presence of some suspended material remaining after centrifugation), 12 stations exceeded the copper CTR value, 6 stations exceeded the lead CTR value, and 12 stations exceeded the total PCBs CTR value. Although the comparisons to the CTR criteria identified several pollutants for which measured pore water concentrations are above levels of concern, the measured pore water concentrations may be biased high due to the possible presence of very fine suspended or colloidal material in the pore water samples that could not be removed by centrifugation.
- 19. FISH HISTOPATHOLOGY.** The Regional Board evaluated fish histopathology data to determine the potential exposure and associated adverse effects on fish from chemical pollutants present within and adjacent to the Shipyard Sediment Site. A total of 253 spotted sand bass were examined for various histopathological lesions. These spotted sand bass were collected from four discrete assessment units at the Shipyard Sediment Site and at a reference area located across San Diego Bay near Reference Station 2240. The fish histopathology data indicates a total of 70 types of histopathological lesions were found in the spotted sand bass. Of the 70 types of lesions found, five lesions exhibited statistically significant elevations relative to reference conditions. The five lesions are abundant lipofuscin in liver,

Revised Tentative Cleanup and Abatement Order No. R9-2005-0126  
Shipyard Sediment Site

April 4, 2008

abundant hemosiderin in liver, cholangitis/biliary hyperplasia (CBH) in liver, nephritis in kidney, and shiny gill foci. A sixth lesion (i.e., foci of cellular alteration in livers) was considered important even though no statistical differences were found because the existence of these lesions indicates a harmful effect strongly linked to PAH exposure. Of the six lesions identified as significantly elevated with respect to reference conditions, two, CBH and foci of cellular alteration, have been identified as being associated with contaminant exposure. Scientific literature describing lesions that are potential biomarkers of environmental stressors in fish does not attribute causation of lipofuscin, hemosiderin, nephritis, and shiny gill foci to pollution-related factors. It is plausible that the lesions could have been caused by naturally occurring environmental factors such as infectious parasites. Based on these considerations the fish histopathology data does not indicate that the fish lesions observed in the data set can be conclusively attributed to contaminant exposure at the Shipyard Sediment Site.

**20. FISH BILE.** The Regional Board evaluated fish bile sampling results to determine the potential exposure of fish to polynuclear aromatic hydrocarbon (PAH) compounds within and adjacent to the Shipyard Sediment Site. The bile samples were analyzed for fluorescent aromatic compounds (FACs) and total proteins. Three groups of FACs were measured that correspond to metabolites (PAH breakdown products) from naphthalene, phenanthrene, and benzo[a]pyrene. Metabolites were detected in bile of spotted sand bass captured inside and outside of the Shipyard Sediment Site and within a reference area located across the bay from the shipyard sites near Reference Station 2240. Metabolites of two contaminants exhibited elevated levels relative to reference conditions in spotted sand bass collected immediately outside of the Shipyard Sediment Site when their mean concentrations were compared against reference data. No metabolites were significantly elevated relative to reference conditions in spotted sand bass collected inside of the Shipyard Sediment Sites.

The upper prediction limit (UPL) at the 95 percent confidence interval was also calculated for the metabolites of the reference area fish and compared to replicate fish bile samples from the four areas of the Shipyard Sediment Site (i.e., inside and outside of both NASSCO and BAE Systems leaseholds). The inside and outside areas of NASSCO had samples that exceeded the UPL. Inside NASSCO accounted for six of the 19 UPL exceedances. Two fish bile samples from inside NASSCO exceeded the UPL for naphthalene, phenanthrene, and benzo[a]pyrene metabolites. From Outside NASSCO, 12 of the 13 UPL exceedances came from phenanthrene and benzo[a]pyrene metabolite samples.

For BAE Systems, all exceedances came from outside BAE Systems of which nine of 11 exceedances were for the benzo [a] pyrene metabolite samples. The remaining two exceedances were for the phenanthrene metabolite samples. No exceedances were found from inside BAE Systems; however, the PAH sediment chemistry data from inside BAE Systems showed the highest levels of sediment contamination.

Revised Tentative Cleanup and Abatement Order No. R9-2005-0126  
 Shipyard Sediment Site

April 4, 2008

The inconsistent relationship between the levels of FACs in fish and PAH contaminated sediment indicates that this data is inconclusive and the FAC concentrations observed in the fish cannot be exclusively attributed to contaminant exposure at the Shipyard Sediment Site. The variable nature of the sediment contamination found in bays and the mobility of the fish are confounding factors when attempting to correlate fish sampling results with sediment contamination.

**21. INDICATOR SEDIMENT CHEMICALS.** The Regional Board evaluated the relationships between sediment chemical pollutants and biological responses to identify indicator chemical pollutants that may be impacting aquatic life and would therefore be candidates for assignment of cleanup levels or remediation goals. A two-step process was conducted. The first step in the selection of indicator chemicals was to identify chemicals representative of the major classes of sediment pollutants: metals, butyltins, PCBs and PCTs, PAHs, and petroleum hydrocarbons. The second step was the evaluation of relationships between these chemicals and biological responses. Results of the three toxicity tests, benthic community assessment, and bioaccumulation testing conducted in Phase 1 of the Shipyard study were all used to evaluate the potential of such relationships. Chemical pollutants were selected as indicator chemicals if they had any statistically significant relationship with amphipod mortality, echinoderm fertilization, bivalve development, total benthic macroinvertebrate abundance, total benthic macroinvertebrate richness, or tissue chemical concentrations in *Macoma nasuta*. Chemical pollutants selected as indicator chemicals include arsenic, copper, lead, mercury, zinc, TBT, total PCB homologs, diesel range organics (DRO), and residual range organics (RRO).

#### *AQUATIC-DEPENDENT WILDLIFE BENEFICIAL USES IMPAIRMENT*

**22. AQUATIC-DEPENDENT WILDLIFE IMPAIRMENT.** Aquatic-dependent wildlife beneficial uses designated for San Diego Bay are impaired due to the elevated levels of pollutants present in the marine sediment at the Shipyard Sediment Site. Aquatic-dependent wildlife beneficial uses include: Wildlife Habitat (WILD), Preservation of Biological Habitats of Special Significance (BIOL), and Rare, Threatened, or Endangered Species (RARE). This finding is based on the considerations described below in the *Impairment of Aquatic-Dependent Wildlife Beneficial Uses* section of the Cleanup and Abatement Order.

**23. RISK ASSESSMENT APPROACH FOR AQUATIC-DEPENDENT WILDLIFE.** The Regional Board evaluated potential risks to aquatic-dependent wildlife from chemical pollutants present in the sediment at the Shipyard Sediment Site based on a two-tier approach. The Tier I screening level risk assessment was based on tissue data derived from the exposure of the clam *Macoma nasuta* to site sediments for 28 days using the protocols specified by American Society of Testing Material (ASTM). The Tier II comprehensive risk assessment was based on tissue data derived from resident fish and shellfish caught within and adjacent to the Shipyard Sediment Site.

Revised Tentative Cleanup and Abatement Order No. R9-2005-0126  
 Shipyard Sediment Site

April 4, 2008

- 24. TIER I SCREENING LEVEL RISK ASSESSMENT FOR AQUATIC-DEPENDENT WILDLIFE.** The Tier I risk assessment objectives were to determine whether or not Shipyard Sediment Site conditions pose a potential unacceptable risk to aquatic-dependent wildlife receptors of concern and to identify whether a comprehensive, site-specific risk assessment was warranted (i.e., Tier II baseline risk assessment). The receptors of concern selected for the assessment include: California least tern (*Sterna antillarum brownie*), California brown pelican (*Pelecanus occidentalis californicus*), Western grebe (*Aechmophorus occidentalis*), Surf scoter (*Melanitta perspicillata*), California sea lion (*Zalophus californianus*), and East Pacific green turtle (*Chelonia mydas agassizii*). Chemical pollutant concentrations measured in clam tissue derived from laboratory bioaccumulation tests were used to estimate chemical exposure to these receptors of concern. Based on the Tier I screening level risk assessment results, there is a potential risk to all receptors of concern ingesting prey caught at the Shipyard Sediment Site. The chemical pollutants in *Macoma* tissue posing a potential risk include arsenic, copper, lead, zinc, benzo[a]pyrene, and total PCBs.
- 25. TIER II BASELINE RISK ASSESSMENT FOR AQUATIC-DEPENDENT WILDLIFE.** The Tier II risk assessment objective was to more conclusively determine whether or not Shipyard Sediment Site conditions pose an unacceptable risk to aquatic-dependent wildlife receptors of concern. The receptors of concern selected for the assessment include: California least tern (*Sterna antillarum brownie*), California brown pelican (*Pelecanus occidentalis californicus*), Western grebe (*Aechmophorus occidentalis*), Surf scoter (*Melanitta perspicillata*), California sea lion (*Zalophus californianus*), and East Pacific green turtle (*Chelonia mydas agassizii*). To focus the risk assessment, prey items were collected within four assessment units at the Shipyard Sediment Site and from a reference area located across the bay from the site. Chemical concentrations measured in fish were used to estimate chemical exposure for the least tern, western grebe, brown pelican, and sea lion and chemical concentrations in benthic mussels and eelgrass were used to estimate chemical pollutant exposure for the surf scoter and green turtle, respectively. Based on the Tier II risk assessment results, ingestion of prey items caught within all four assessment units at the Shipyard Sediment Site poses a risk to all receptors of concern (excluding the sea lion). The chemical in prey tissue posing a risk include benzo[a]pyrene, total PCBs, copper, lead, mercury, and zinc.

#### *HUMAN HEALTH BENEFICIAL USES IMPAIRMENT*

- 26. HUMAN HEALTH IMPAIRMENT.** Human health beneficial uses designated for San Diego Bay are impaired due to the elevated levels of pollutants present in the marine sediment at the Shipyard Sediment Site. Human health beneficial uses include: Contact Water Recreation (REC-1), Non-contact Water Recreation (REC-2), Shellfish Harvesting (SHELL), and Commercial and Sport Fishing (COMM). This finding is based on the considerations described below in this *Impairment of Human Health Beneficial Uses* section of the Cleanup and Abatement Order.

Revised Tentative Cleanup and Abatement Order No. R9-2005-0126  
Shipyard Sediment Site

April 4, 2008

**27. RISK ASSESSMENT APPROACH FOR HUMAN HEALTH.** The Regional Board evaluated potential risks to human health from chemical pollutants present in the sediment at the Shipyard Sediment Site based on a two-tier approach. The Tier I screening level risk assessment was based on tissue data derived from the exposure of the clam *Macoma nasuta* to site sediments for 28 days using American Society of Testing Material (ASTM) protocols. The Tier II comprehensive risk assessment was based on tissue data derived from resident fish and shellfish caught within and adjacent to the Shipyard Sediment Site. Two types of receptors (i.e., members of the population or individuals at risk) were evaluated:

- a. Recreational Anglers – Persons who eat the fish and/or shellfish they catch recreationally; and
- b. Subsistence Anglers – Persons who fish for food, for economic and/or cultural reasons, and for whom the fish and/or shellfish caught is a major source of protein in their diet.

**28. TIER I SCREENING LEVEL RISK ASSESSMENT FOR HUMAN HEALTH.** The Tier I risk assessment objectives were to determine whether or not Shipyard Sediment Site conditions potentially pose an unacceptable risk to human health and to identify if a comprehensive, site-specific risk assessment was warranted (i.e., Tier II baseline risk assessment). The receptors of concern identified for Tier I are recreational anglers and subsistence anglers. Recreational anglers represent those who eat the fish and/or shellfish they catch recreationally and subsistence anglers represent those who fish for food, for economic and/or cultural reasons, and for whom the fish and/or shellfish caught is a major source of protein in the diet. Chemical concentrations measured in *Macoma nasuta* tissue derived from laboratory bioaccumulation tests were used to estimate chemical exposure for these receptors of concern. Based on the Tier I screening level risk assessment results, there is a potential risk to recreational and subsistence anglers ingesting fish and shellfish caught at the Shipyard Sediment Site. The chemicals in *Macoma* tissue posing a potential risk include arsenic, BAP, PCBs, and TBT.

**29. TIER II BASELINE RISK ASSESSMENT FOR HUMAN HEALTH.** The Tier II risk assessment objective was to more conclusively determine whether Shipyard Sediment Site conditions pose unacceptable cancer and non-cancer health risks to recreational and subsistence anglers. Fish and shellfish were collected within four assessment units at the Shipyard Sediment Site and from two reference areas located across the bay from the Shipyard Site. Chemical concentrations measured in fish fillets and edible shellfish tissue were used to estimate chemical exposure for recreational anglers and chemical concentrations in fish whole bodies and shellfish whole bodies were used to estimate chemical exposure for subsistence anglers. Based on the Tier II risk assessment results, ingestion of fish and shellfish caught within all four assessment units at the Shipyard Sediment Site poses a theoretical increased cancer and non-cancer risk to recreational and subsistence anglers. The chemicals posing cancer risks include inorganic arsenic and PCBs. The chemicals posing non-cancer risks include cadmium, copper, mercury, and total PCBs.

Revised Tentative Cleanup and Abatement Order No. R9-2005-0126  
Shipyard Sediment Site

April 4, 2008

**CLEANUP TO BACKGROUND SEDIMENT QUALITY CONDITIONS**

**30. BACKGROUND SEDIMENT QUALITY.** The Regional Board derived sediment chemistry levels for use in evaluating the feasibility of cleanup to background sediment quality conditions from the pool of San Diego Bay reference stations described in Finding 15. The background sediment chemistry levels based on these reference stations are as follows:

**Background Sediment Chemistry Levels**

Chemical	Units (dry weight)	Background Sediment Chemistry Levels <sup>(1)</sup>
Metals		
Arsenic	mg/kg	7.5
Cadmium	mg/kg	0.33
Chromium	mg/kg	57
Copper	mg/kg	121
Lead	mg/kg	53
Mercury	mg/kg	0.57
Nickel	mg/kg	15
Silver	mg/kg	1.1
Zinc	mg/kg	192
Organics		
Dibutyltin	µg/kg	21
Monobutyltin	µg/kg	14
Tributyltin	µg/kg	22
Tetrabutyltin	µg/kg	(1.4)
HPAH <sup>(2)</sup>	µg/kg	673
PPPAH <sup>(3)</sup>	µg/kg	1,234
Benzo[a]pyrene	µg/kg	202
Total PCB Congeners <sup>(4)</sup>	µg/kg	84
Polychlorinated terphenyls	µg/kg	(142)

(1) Based on the 95 percent upper prediction limit calculated from a pool of reference stations in San Diego Bay. Parentheses ( ) indicates non-detects accounted for more than or equal to half the values.

(2) HPAH = High Molecular Weight Polynuclear Aromatic Hydrocarbons

(3) PPPAH = Priority Pollutant Polynuclear Aromatic Hydrocarbons

(4) PCB = Polychlorinated Biphenyls

Note: A regression analysis of the grain size:metals relationship is used in establishing background sediment chemistry levels. The background metals concentration is based on the 95% UPL using 50% fine grain sediment. These values are conservative concentrations because the mean fine grain sediment at the Shipyard Investigation Site is 70% fine grain sediment. See Appendix for Section 15 of the Draft Technical Report for Tentative Cleanup and Abatement Order No. R9-2005-0126 for further details on the regression analysis.

Revised Tentative Cleanup and Abatement Order No. R9-2005-0126  
Shipyard Sediment Site

April 4, 2008

**31. TECHNOLOGICAL FEASIBILITY CONSIDERATIONS.** It is technologically feasible to cleanup to background sediment quality levels at the Shipyard Sediment Site. The Regional Board considered three remedial technologies for the cleanup to background evaluation: (1) Natural Recovery, (2) Subaqueous Capping, and (3) Dredging. Based on current site use, natural recovery is considered to be technologically infeasible due to sediment disturbance from normal shipyard activities (e.g., vessel propeller wash, ship traffic, dry dock movements, maintenance/navigational dredging, engine tests, construction, etc.). Subaqueous capping is also considered to be technologically infeasible based on current site use because of the ever-larger ships being serviced at the shipyards, the associated navigational requirements, and the likelihood of cap disturbance resulting from normal shipyard activities (e.g., vessel propeller wash). Dredging, although difficult to implement because the Shipyard Sediment Site is currently a working shipyard, is considered to be technologically feasible. Dredging is a proven technology and it has been used not only in San Diego Bay but also throughout the United States for remediation of contaminated sediment.

**32. ECONOMIC FEASIBILITY CONSIDERATIONS.** The Regional Board evaluated a number of criteria to determine tradeoffs in risks, costs, and benefits associated with cleanups to background sediment chemistry levels and six alternative cleanup levels greater than background. The criteria included factors such as total cost, volume of sediment dredged, short- and long-term effects on beneficial uses (aquatic life, aquatic-dependent wildlife, and human health), effects on shipyards and associated economic activities, effects on local businesses and neighborhood quality of life, and effects on recreational, commercial, or industrial uses of aquatic resources. Based on these considerations, the Regional Board concludes that it is not economically feasible to cleanup to the background sediment chemistry levels.

#### *ALTERNATIVE SEDIMENT CLEANUP LEVELS*

**33. ALTERNATIVE CLEANUP LEVELS.** The Regional Board has selected the alternative cleanup levels presented below for the Shipyard Sediment Site. In approving alternative cleanup levels less stringent than background the Regional Board has considered the factors contained in Resolution 92-49 and the California Code of Regulations, Title 23, section 2550.4, subdivision (d)<sup>1</sup>.

- a. *Alternative Cleanup Levels are Appropriate.* The Regional Board has determined that it is economically infeasible to cleanup to background sediment quality levels at the Shipyard Sediment Site. The overall benefit of remediating the site to the alternative cleanup levels is approximately equal to the overall benefit of cleaning up to background for considerably less cost.

---

<sup>1</sup> Resolution 92-49 provides that in approving any alternative cleanup levels less stringent than background sediment quality the Regional Board must consider the conditions described in California Code of Regulations, Title 23, section 2550.4. Resolution 92-49 further requires that any alternative cleanup levels shall (1) be consistent with maximum benefit to the people of the state; (2) not unreasonably affect present and anticipated beneficial use of such water; and (3) not result in water quality less than that prescribed in the Water Quality Control Plans and Policies adopted by the State and Regional Water Boards.

Revised Tentative Cleanup and Abatement Order No. R9-2005-0126  
Shipyard Sediment Site

April 4, 2008

- b. ***Alternative Cleanup Levels Are Consistent With Water Quality Control Plans And Policies.*** The alternative cleanup levels will not result in water quality less than prescribed in water quality control plans and policies adopted by the State Water Resources Control Board and the Regional Board<sup>2</sup>. The alternative sediment quality levels are well below levels expected to cause toxicity to aquatic life and will substantially reduce existing risks to aquatic dependent wildlife and human health.
- c. ***Alternative Cleanup Levels Are Consistent With The Maximum Benefit To The People Of The State.*** The level of water quality that will be attained upon implementation of the alternative cleanup levels at the Shipyard Sediment Site is consistent with the maximum benefit to the people of the state. The San Diego Bay shoreline between Sampson and 28th Streets is listed on the Clean Water Act 303(d) list for elevated levels of copper, mercury, PAHs, and PCBs at the Shipyard Sediment Site. While it is impossible to determine the precise level of water quality that will be attained given the residual sediment pollutants constituents that will remain at the site, compliance with the alternative cleanup levels will markedly improve water quality conditions in the Shipyard Sediment Site and result in attainment of water quality standards at the site.

---

<sup>2</sup> Applicable numerical and narrative water quality objectives for San Diego Bay Waters include the Regional Board's Toxicity Objective, the California Toxics Rule Water Quality Criteria and the State Water Board Policy for Implementation of Toxics Standards (the SIP) which provides that mixing zones shall not result in "objectionable bottom deposits." This term is defined as "an accumulation of materials ... on or near the bottom of a water body which creates conditions that adversely impact aquatic life, human health, beneficial uses, or aesthetics. These conditions include, but are not limited to, the accumulation of pollutants in the sediments (SWRCB, 2005).

Revised Tentative Cleanup and Abatement Order No. R9-2005-0126  
Shipyard Sediment Site

April 4, 2008

#### Alternative Sediment Cleanup Levels

Chemical	Units (dry weight)	Alternative Sediment Cleanup Levels <sup>(1)</sup>
<b>Metals</b>		
Arsenic	mg/kg	10
Cadmium	mg/kg	1.0
Chromium	mg/kg	81
Copper	mg/kg	200
Lead	mg/kg	90
Mercury	mg/kg	0.7
Nickel	mg/kg	20
Silver	mg/kg	1.5
Zinc	mg/kg	300
<b>Organics</b>		
Tributyltin	µg/kg	110
Benzo[a]pyrene	µg/kg	1,010
Total PCB Congeners <sup>(2)</sup>	µg/kg	420

- 1) Cleanup levels for tributyltin, benzo[a]pyrene, and total PCB congeners are based on 5 times background, constituents which, at 5 times background, determine the largest cleanup footprint. The other chemical concentrations are based on an evaluation of that cleanup footprint.
- 2) PCB = polychlorinated biphenyl

**34. LEGAL AND REGULATORY AUTHORITY.** This Order is based on (1) section 13267 and Chapter 5, Enforcement, of the Porter-Cologne Water Quality Control Act (Division 7 of the Water Code, commencing with section 13000), commencing with section 13300; (2) applicable state and federal regulations; (3) all applicable provisions of statewide Water Quality Control Plans adopted by the State Water Resources Control Board and the *Water Quality Control Plan for the San Diego Basin* (Basin Plan) adopted by the Regional Board including beneficial uses, water quality objectives, and implementation plans; (4) State Water Board policies for water quality control, including State Water Board Resolution No. 68-16 (*Statement of Policy with Respect to Maintaining High Quality of Waters in California*) and Resolution No. 92-49 (*Policies and Procedures for Investigation and Cleanup and Abatement of Discharges Under Water Code section 13304*); and (5) relevant standards, criteria, and advisories adopted by other state and federal agencies.

Revised Tentative Cleanup and Abatement Order No. R9-2005-0126  
Shipyard Sediment Site

April 4, 2008

**35. CEQA EXEMPTION.** This enforcement action is exempt from the provisions of the California Environmental Quality Act (CEQA) because it falls within Classes 7, 8, and 21 of the categorical exemptions for projects that have been determined not to have a significant effect on the environment under section 21084 of CEQA. [14 CCR 15307, 15308, and 15321.] The Regional Board will not undertake any construction activity as a result of this Order, nor will the issuance of this Order allow environmental degradation.

**36. PUBLIC NOTICE.** The Regional Board has notified all known interested persons and the public of its intent to adopt this Cleanup and Abatement Order and has provided them with an opportunity to submit written comments and recommendations.

**37. PUBLIC HEARING.** The Regional Board has considered all comments pertaining to this Cleanup and Abatement Order submitted to the Regional Board in writing, or by oral presentations at the public hearing held on [date(s) to be inserted]. Detailed responses to relevant comments have been incorporated into the final Technical Report for the Cleanup and Abatement Order adopted by this Order.

**38. TECHNICAL REPORT.** The attached "Draft Technical Report for Tentative Cleanup and Abatement Order No. R9-2005-0126" is hereby incorporated as a finding in support of this Cleanup and Abatement Order as if fully set forth here verbatim.

#### *ORDER DIRECTIVES*

**IT IS HEREBY ORDERED that, pursuant to sections 13267 and 13304 of the Water Code, National Steel and Shipbuilding Company; BAE Systems San Diego Ship Repair Inc. (formerly Southwest Marine, Inc.); City of San Diego; Marine Construction and Design Company and Campbell Industries, Inc; San Diego Gas and Electric, a subsidiary of Sempra Energy Company; and the United States Navy (hereinafter Discharger(s)), shall comply with the following directives:**

##### **A. CLEANUP AND ABATE**

1. **Terminate Illicit Discharges.** The Discharger(s) shall terminate all illicit discharges to San Diego Bay in violation of waste discharge requirements or other order or prohibition issued by the Regional Board.

Revised Tentative Cleanup and Abatement Order No. R9-2005-0126  
Shipyard Sediment Site

April 4, 2008

- 2. Corrective Actions.** The Discharger(s) shall take all corrective actions<sup>3</sup> necessary to cleanup contaminated marine bay sediment at the Shipyard Sediment Site to attain the sediment quality levels specified below:

Chemical	Units (dry weight)	Sediment Quality Levels
<b>Inorganics</b>		
Arsenic	mg/kg	10
Cadmium	mg/kg	1.0
Chromium	mg/kg	81
Copper	mg/kg	200
Lead	mg/kg	90
Mercury	mg/kg	0.7
Nickel	mg/kg	20
Silver	mg/kg	1.5
Zinc	mg/kg	300
<b>Organics</b>		
Tributyltin	µg/kg	110
Benzo[a]pyrene	µg/kg	1,010
Total PCB Congeners <sup>(1)</sup>	µg/kg	420

(1) PCB = polychlorinated biphenyl

- 3. Site Investigation.** San Diego Gas and Electric, a subsidiary of Sempra Energy Company, (SDG&E) shall prepare and submit a Site Investigation Report (Report) by [date based on 45 days after adoption to be inserted] containing the following information:
- Site Conceptual Model.* The Report shall contain a site conceptual model showing all the current and former potential pathways for pollutants to potentially discharge from the SDG&E property to the Shipyard Sediment Site, including all elements of the Storm Water Conveyance System (SWCS) between the SDG&E property and San Diego Bay.
  - Source Characterization.* The Report shall describe the results of an investigation of all potential sources of waste discharges to surface soils and storm water conveyance systems based on historical records of operation, site reconnaissance, and previous sampling studies. Potential sources that should be investigated include current or

---

<sup>3</sup> Corrective Actions include the phases of cleanup and abatement described in Directives A through D of this Cleanup and Abatement order.

Revised Tentative Cleanup and Abatement Order No. R9-2005-0126  
Shipyard Sediment Site

April 4, 2008

former locations of tanks, drains, sumps, areas of stained soil, container storage areas, transformers, and other areas where waste constituents were handled, stored, or used. All current or former locations of sources of waste constituents shall be located on a site map at a scale of 1 inch = 200 feet or larger, with graphics indicating surface water drainage directions on and adjacent to the SDG&E property.

- c. *Storm Water Conveyance System (SWCS) Characterization.* The Report shall characterize the presence of waste constituents in loose and cemented sediment found in the SWCS, including catch basins tributary to the SWCS on and adjacent to the SDG&E property, and between the SDG&E property and San Diego Bay.
- d. *Extent of Waste Constituent Characterization.* The Report shall characterize the lateral and vertical extent of each waste constituent above the background<sup>4</sup> value for that waste constituent.
- e. *Chemical Analyses.* The report shall describe the laboratory analytical methods and protocols used for each sample analysis. The suite of chemical analyses must be adequate to identify the full range of site-specific waste constituents including, at a minimum, polychlorinated biphenyls, copper, lead, zinc, total petroleum hydrocarbons (TPH), and benzo(a)pyrene.<sup>5</sup>
- f. *Sample Locations and Number.* The locations, type, and number of samples shall be identified and shown on a site map and cross sections. The number of samples and suite of chemical analyses must be sufficient to identify the nature of waste constituent sources, to define the distribution of waste constituents on the ground surface and in the SWCS on the SDG&E property and between the SDG&E property and San Diego Bay.

## B. REMEDIAL ACTION PLAN AND IMPLEMENTATION

- 1. *Remedial Action Plan (RAP).* The Discharger(s) shall submit a Remedial Action Plan (RAP) to the Regional Board by [date based on 90 days after adoption to be inserted]. The RAP shall contain the following information:
  - a. *Implementation Activities.* A detailed description of all activities planned to implement the corrective actions necessary to comply with all the directives herein;
  - b. *Shipyard Sediment Site Map.* A map(s), using an appropriate modeling program, illustrating the horizontal and vertical distribution of pollutants within the remediation area defined by the sediment quality cleanup levels described in Directive A.1;
  - c. *Schedule.* A schedule detailing the sequence of events and time frame for each activity; and

---

<sup>4</sup> "Background" is defined as the concentration or measures of constituents or indicator parameters in soil that have not been affected by waste constituents released from the SDG&E property.

<sup>5</sup> These waste constituents, except for benzo(a)pyrene, were reported in elevated concentrations in surface soil samples from the SDG&E property [see Section 8.9 of the Draft Technical Report]. Benzo(a)pyrene is a component of the TPH reported in elevated concentrations in the surface soil samples from the SDG&E property.

Revised Tentative Cleanup and Abatement Order No. R9-2005-0126  
Shipyard Sediment Site

April 4, 2008

- d. *Short-Term Effectiveness Monitoring Activities.* A monitoring program as described in Directive C, Cleanup and Abatement Verification, to demonstrate the effectiveness of the RAP. The monitoring program shall be effective in determining compliance with the cleanup levels and in determining the success of the remedial action measures.
2. *Remedial Action Plan (RAP) Implementation.* In the interest of promoting prompt cleanup, the Discharger(s) may begin implementation of the RAP sixty (60) calendar days after submittal to the Regional Board, unless otherwise directed in writing by the Regional Board. Before beginning RAP implementation activities, the Discharger(s) shall:
  - a. Notify the Regional Board of its intention to begin cleanup; and
  - b. Comply with any conditions set by the Regional Board, including mitigation of adverse consequences from cleanup activities.
3. *Remedial Action Zone.* The Discharger(s) shall implement remedial action measures that ensure that marine sediment pollutants attain their respective cleanup levels at all monitoring points and throughout the Shipyard Sediment Site.
4. *Implementation Schedule.* Implementation of the RAP shall be completed on a schedule to be established by the Regional Board in a subsequent amendment to this Cleanup and Abatement Order.
5. *Monitoring, Evaluation, and Reporting.* The Discharger(s) shall monitor, evaluate, and report the results of implementation of the RAP on a schedule to be established by the Regional Board in a subsequent amendment to this Cleanup and Abatement Order.
6. *Modify or Suspend Cleanup Activities.* The Discharger(s) shall modify or suspend cleanup activities when directed to do so by the Regional Board.

## C. CLEANUP AND ABATEMENT COMPLETION VERIFICATION

1. *Cleanup and Abatement Completion Report.* The Discharger(s) shall submit a final Cleanup and Abatement Completion Report verifying completion of the Remedial Action Plan (RAP) for the Shipyard Sediment Site. The report shall provide a demonstration, based on a sound technical analysis that marine sediment quality cleanup levels specified in Directive A.1. for all pollutants are attained at all monitoring points and throughout the Shipyard Sediment Site.

Revised Tentative Cleanup and Abatement Order No. R9-2005-0126  
Shipyard Sediment Site

April 4, 2008

#### D. POST CLEANUP MONITORING

1. ***Post Cleanup Monitoring Plan.*** The Discharger(s) shall submit a Post Cleanup Monitoring Plan to the Regional Board by [Insert Date]. The Post Cleanup Monitoring Plan shall be designed to confirm the short-term and long-term effectiveness of the cleanup. The Post Cleanup Monitoring Plan shall contain the following information:
  - a. ***Monitoring Activities.*** A detailed description of monitoring and sampling activities designed to assess the site conditions, including the benthic community health, after the RAP is completed. The monitoring activities shall include sampling for a period of not less than five years; and
  - b. ***Schedule.*** A schedule detailing the sequence of events and time frame for each activity. The schedule shall also include the dates for submittal of the Post-Cleanup Monitoring annual progress reports and final report as detailed in Section D.2. below.
2. ***Post Cleanup Monitoring Report.*** The Discharger shall submit annual progress reports and a final Post Cleanup Monitoring Report, on a schedule to be established by the Regional Board in a subsequent amendment to this Cleanup and Abatement Order, containing the following information:
  - a. ***Monitoring Activities.*** A detailed description of the post cleanup monitoring activities performed; and
  - b. ***Interpretations and Conclusions.*** Interpretations and conclusions regarding the potential presence and chemical characteristics of any newly deposited sediment within the cleanup areas, and interpretations and conclusions regarding the health and recovery of the benthic communities.

#### E. REGIONAL BOARD CONCURRENCE

1. ***Regional Board Concurrence.*** Upon concurrence with the findings of the Cleanup and Abatement Completion Report (Directive C.1) and the Post Cleanup Monitoring Report (Directive D.2) that remedial actions and monitoring are complete and that compliance with this Cleanup and Abatement Order is achieved, the Regional Board will inform the Discharger(s) and other interested persons in writing that no further remedial work is required at this time, based on available information. This written notice shall constitute Regional Board concurrence with the completed remedial actions.

Revised Tentative Cleanup and Abatement Order No. R9-2005-0126  
Shipyard Sediment Site

April 4, 2008

## F. PROVISIONS

1. ***Cost Recovery.*** The Discharger(s) shall reimburse the State of California for all reasonable costs actually incurred by the Regional Board to investigate, oversee, and monitor cleanup and abatement actions required by this Cleanup and Abatement Order, according to billing statements prepared from time to time by the State Water Resources Control Board. If the Discharger(s) is enrolled in a reimbursement program managed by the State Water Resources Control Board for the discharge addressed by this Cleanup and Abatement Order, reimbursement shall be made pursuant to the procedures established in that program.
2. ***Waste Management.*** The Discharger(s) shall properly manage, store, treat, and dispose of contaminated soils and ground water in accordance with applicable federal, state, and local laws and regulations. The storage, handling, treatment, or disposal of contaminated marine sediment and associated waste shall not create conditions of pollution, contamination or nuisance as defined in Water Code section 13050. The Discharger(s) shall, as required by the Regional Board, obtain, or apply for coverage under, waste discharge requirements or a conditional waiver of waste discharge requirements for the removal of waste from the immediate place of release and discharge of the waste to (a) land for treatment, storage, or disposal or (b) waters of the state.
3. ***Request to Provide Information.*** The Discharger(s) may present characterization data, preliminary interpretations and conclusions as they become available, rather than waiting until a final report is prepared. This type of on-going reporting can facilitate a consensus being reached between the Discharger(s) and the Regional Board and may result in overall reduction of the time necessary for regulatory approval.
4. ***Waste Constituent Analysis.*** Unless otherwise permitted by the Regional Board, all analyses shall be conducted at a laboratory certified for such analyses by the State Department of Health Services. Specific methods of analysis must be identified. If the Discharger(s) proposes to use methods or test procedures other than those included in the most current version of "*Test Methods for Evaluating Solid Waste, Physical/Chemical Methods, SW-846*" (U.S. Environmental Protection Agency) or 40 CFR 136, "*Guidelines Establishing Test Procedures for the Analysis of Pollutants; Procedures for Detection and Quantification*", the exact methodology must be submitted for review and must be approved by the Regional Board prior to use. The director of the laboratory whose name appears on the certification shall supervise all analytical work in his/her laboratory and shall sign all reports submitted to the Regional Board.
5. ***Duty to Operate and Maintain.*** The Discharger(s) shall, at all times, properly operate and maintain all facilities and systems of treatment, control, storage, disposal and monitoring (and related appurtenances) which are installed or used by the Discharger(s) to achieve compliance with this Cleanup and Abatement Order. Proper operation and maintenance also includes adequate laboratory controls and appropriate quality assurance procedures. This provision requires the operation of back-up or auxiliary facilities, which are installed by the Discharger(s) only when the operation is necessary to achieve compliance the conditions of this Cleanup and Abatement Order.

Revised Tentative Cleanup and Abatement Order No. R9-2005-0126  
Shipyard Sediment Site

April 4, 2008

6. **Duty to Use Registered Professionals.** The Discharger(s) shall provide documentation that plans and reports required under this Cleanup and Abatement Order are prepared under the direction of appropriately qualified professionals. California Business and Professions Code sections 6735, 7835 and 7835.1 require that engineering and geologic evaluations and judgments be performed by or under the direction of registered professionals. A statement of qualifications and registration numbers of the responsible lead professionals shall be included in all plans and reports submitted by the Discharger(s). The lead professional shall sign and affix their registration stamp to the report, plan or document.
7. **Corporate Signatory Requirements.** All reports required under this Order shall be signed and certified by a responsible corporate officer(s) of the Discharger(s) described in paragraph 5.a. of this provision or by a duly authorized representative of that person as described in paragraph 5.b.of this provision.
  - a. **Responsible Corporate Officer(s).** For the purposes of this provision, a responsible corporate officer means: (i) A president, secretary, treasurer, or vice-president of the corporation in charge of a principal business function, or any other person who performs similar policy - or decision-making functions for the corporation, or (ii) the manager of one or more manufacturing, production, or operating facilities, provided, the manager is authorized to make management decisions which govern the operation of the regulated facility including having the explicit or implicit duty of making major capital investment recommendations, and initiating and directing other comprehensive measures to assure long term environmental compliance with environmental laws and regulations; the manager can ensure that the necessary systems are established or actions taken to gather complete and accurate information for permit application requirements; and where authority to sign documents has been assigned or delegated to the manager in accordance with corporate procedures.
  - b. **Duly Authorized Representative.** A person is a duly authorized representative only if:
    - (1) The authorization is made in writing by a person described in paragraph (a) of this provision;
    - (2) The authorization specifies either an individual or a position having responsibility for the overall operation of the regulated facility or activity such as the position of plant manager, operator of a well or a well field, superintendent, position of equivalent responsibility, or an individual (A duly authorized representative may thus be either a named individual or any individual occupying a named position.); and
    - (3) The written authorization is submitted to the Regional Board.

Revised Tentative Cleanup and Abatement Order No. R9-2005-0126  
Shipyard Sediment Site

April 4, 2008

- c. *Changes to Authorization.* If an authorization under paragraph (b) of this provision is no longer accurate because a different individual or position has responsibility for the overall operation of the facility, a new authorization satisfying the requirements of paragraph (b) of this provision must be submitted to the Regional Board prior to or together with any reports or information to be signed by an authorized representative.
- d. *Certification Statement.* Any person signing a document under paragraph a. or b. of this provision shall make the following certification:

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

8. *Duty to Submit Other Information.* When the Discharger(s) becomes aware that it failed to submit any relevant facts in any report required under this Cleanup and Abatement Order, or submitted incorrect information in any such report, the Discharger(s) shall promptly submit such facts or information to the Regional Board.
9. *Electronic and Paper Media Reporting Requirements.* The Discharger(s) shall submit both electronic and paper copies of all reports required under this Cleanup and Abatement Order including work plans, technical reports, and monitoring reports.
10. *Report Submittals.* All monitoring and technical reports required under this Cleanup and Abatement Order shall be submitted to:

Executive Officer  
California Regional Water Quality Control Board  
San Diego Region  
9174 Sky Park Court, Suite 100  
San Diego, CA 92123-4340

11. *Identify Documents Using Code Number.* In order to assist the Regional Board in the processing of correspondence and reports submitted in compliance with this Cleanup and Abatement Order, the Discharger(s) shall include the following code number in the header or subject line portion of all correspondence or reports submitted to the Regional Board:

For all correspondences: **Shipyards CAO: 03-0284.05**  
For all reports: **Shipyards CAO: 03-0284.051**

Revised Tentative Cleanup and Abatement Order No. R9-2005-0126  
 Shipyard Sediment Site

April 4, 2008

12. ***Amendment.*** This Cleanup and Abatement Order in no way limits the authority of this Regional Board to institute additional enforcement actions or to require additional investigation and cleanup consistent with the California Water Code. This Cleanup and Abatement Order may be revised by the Regional Board as additional information becomes available.
13. ***Time Extensions.*** If, for any reason, the Dischargers are unable to perform any activity or submit any documentation in compliance with requirements in this Cleanup and Abatement Order, including the RAP, or in compliance with associated implementation schedules, including the RAP implementation schedule, the Dischargers may request, in writing, an extension of time. The written extension request shall include justification for the delay and shall be received by the Regional Board reasonably (but not less than 15 calendar days) in advance of the deadline sought to be extended. An extension may be granted for good cause, in which case this Cleanup and Abatement Order will be accordingly amended.

#### G. NOTIFICATIONS

1. ***Enforcement Discretion.*** The Regional Board reserves its right to take any enforcement action authorized by law for violations of the terms and conditions of this Cleanup and Abatement Order.
2. ***Enforcement Notification.*** The Porter-Cologne Water Quality Control Act commencing with Chapter 5, Enforcement and Implementation, section 13308, provides that if there is a threatened or continuing violation of a cleanup and abatement order, the Regional Board may issue a Time Schedule Order prescribing a civil penalty in an amount not to exceed \$10,000 per day for each day compliance is not achieved in accordance with that time schedule. Section 13350 provides that any person may be assessed administrative civil liability by the Regional Board for violating a cleanup and abatement order in an amount not to exceed \$5,000 for each day the violation occurs, or on a per gallon basis, not to exceed \$10 for each gallon of waste discharged. Alternatively the court may impose civil liability in an amount not to exceed \$15,000 for each day the violation occurs, or on a per gallon basis, not to exceed \$20 for each gallon of waste discharged. Section 13385 provides that any person may be assessed administrative civil liability by the Regional Board for violating a cleanup and abatement order for an activity subject to regulation under Division 7, Chapter 5.5 of the Water Code, in an amount not to exceed the sum of both of the following: (1) \$10,000 for each day in which the violation occurs; and (2) where there is a discharge, any portion of which is not susceptible to cleanup or is not cleaned up, and the volume discharged but not cleaned up exceeds 1,000 gallons, an additional liability not to exceed \$10 multiplied by the number of gallons by which the volume discharged but not cleaned up exceeds 1,000 gallons. Alternatively the civil liability may be imposed by the court in an amount not to exceed the sum of both of the following: (1) \$25,000 for each day in which the violation occurs; and (2) where there is a discharge, any portion of which is not susceptible to cleanup or is not cleaned up, and the volume discharged but not cleaned up exceeds 1,000 gallons, an additional liability not to exceed \$25 multiplied by the number of gallons by which the volume discharged but not cleaned up exceeds 1,000 gallons.

Revised Tentative Cleanup and Abatement Order No. R9-2005-0126  
Shipyard Sediment Site

April 4, 2008

I, John H. Robertus, Executive Officer, do hereby certify the forgoing is a full, true, and correct copy of a Cleanup and Abatement Order issued on [Insert Date].

---

John H. Robertus  
Executive Officer

Attachment 1. Map of Shipyard Sediment Site (Exponent, 2003)



## CIVIL COVER SHEET

JS 44 (Rev. 12/07)

The JS 44 civil cover sheet and the information contained herein neither replace nor supplement the filing and service of pleadings or other papers as required by law, except as provided by local rules of court. This form, approved by the Judicial Conference of the United States in September 1974, is required for the use of the Clerk of Court for the purpose of initiating the civil docket sheet. (SEE INSTRUCTIONS ON THE REVERSE OF THE FORM.)

## I. (a) PLAINTIFFS

CITY OF SAN DIEGO

## DEFENDANTS

NATIONAL STEEL &amp; SHIPBUILDING COMPANY. (PLEASE SEE ATTACHMENT "A")

09 OCT 14 PM 12:29

(b) County of Residence of First Listed Plaintiff SAN DIEGO  
(EXCEPT IN U.S. PLAINTIFF CASES)County of Residence of First Listed Defendant U.S. DISTRICT COURT  
(IN U.S. PLAINTIFF CASES ONLY)

NOTE: IN LAND CONDEMNATION CASES, USE THE LOCATION OF THE LAND INVOLVED.

Attorneys (If Known)

BY:

*[Signature]*

DEPUTY

(c) Attorney's (Firm Name, Address, and Telephone Number)  
Brian M. Ledger  
GORDON & REES LLP  
101 W. Broadway, Ste. 1600  
San Diego, CA 92101  
Tel. (619) 696-6700 / Fax (619) 696-7124

## II. BASIS OF JURISDICTION (Place an "X" in One Box Only)

- |   |  |
|---|--|
| <input type="checkbox"/> 1 U.S. Government Plaintiff            | <input type="checkbox"/> 3 Federal Question (U.S. Government Not a Party)          |
| <input checked="" type="checkbox"/> 2 U.S. Government Defendant | <input type="checkbox"/> 4 Diversity (Indicate Citizenship of Parties in Item III) |

## III. CITIZENSHIP OF PRINCIPAL PARTIES (Place an "X" in One Box for Plaintiff and One Box for Defendant)

Citizen of This State	PTF	DEF	PTF	DEF
<input type="checkbox"/> 1 Incorporated or Principal Place of Business In This State	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> 4	<input type="checkbox"/> 4
<input type="checkbox"/> 2 Incorporated and Principal Place of Business In Another State	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> 3 Foreign Nation	<input type="checkbox"/>	<input type="checkbox"/> 3	<input type="checkbox"/>	<input type="checkbox"/> 6

*[Large FAXED stamp]*

## IV. NATURE OF SUIT (Place an "X" in One Box Only)

CONTRACT	TORTS	FORFEITURE/PENALTY	BANKRUPTCY	OTHER STATUTES
<input type="checkbox"/> 110 Insurance	<input type="checkbox"/> PERSONAL INJURY	<input type="checkbox"/> PERSONAL INJURY	<input type="checkbox"/> 422 Appeal 28 USC 158	<input type="checkbox"/> 400 State Reapportionment
<input type="checkbox"/> 120 Marine	<input type="checkbox"/> 310 Airplane	<input type="checkbox"/> 362 Personal Injury—Med. Malpractice	<input type="checkbox"/> 423 Withdrawal	<input type="checkbox"/> 410 Antitrust
<input type="checkbox"/> 130 Miller Act	<input type="checkbox"/> 315 Airplane Product Liability	<input type="checkbox"/> 365 Personal Injury—Product Liability	28 USC 157	<input type="checkbox"/> 430 Banks and Banking
<input type="checkbox"/> 140 Negotiable Instrument	<input type="checkbox"/> 320 Assault, Libel & Slander	<input type="checkbox"/> 368 Asbestos Personal Injury Product Liability		<input type="checkbox"/> 450 Commerce
<input type="checkbox"/> 150 Recovery of Overpayment & Enforcement of Judgment	<input type="checkbox"/> 330 Federal Employers' Liability	<input type="checkbox"/> 370 Other Fraud		<input type="checkbox"/> 460 Deportation
<input type="checkbox"/> 151 Medicare Act	<input type="checkbox"/> 340 Marine	<input type="checkbox"/> 371 Truth in Lending		<input type="checkbox"/> 470 Racketeer Influenced and Corrupt Organizations
<input type="checkbox"/> 152 Recovery of Defaulted Student Loans (Excl. Veterans)	<input type="checkbox"/> 345 Marine Product Liability	<input type="checkbox"/> 380 Other Personal Property Damage	<input type="checkbox"/> 820 Copyrights	<input type="checkbox"/> 480 Consumer Credit
<input type="checkbox"/> 153 Recovery of Overpayment of Veteran's Benefits	<input type="checkbox"/> 350 Motor Vehicle	<input type="checkbox"/> 385 Property Damage Product Liability	<input type="checkbox"/> 830 Patent	<input type="checkbox"/> 490 Cable/Sat TV
<input type="checkbox"/> 160 Stockholders' Suits	<input type="checkbox"/> 355 Motor Vehicle Product Liability	<input type="checkbox"/> 390 Other	<input type="checkbox"/> 840 Trademark	<input type="checkbox"/> 810 Selective Service
<input type="checkbox"/> 190 Other Contract	<input type="checkbox"/> 360 Other Personal Injury			<input type="checkbox"/> 850 Securities/Commodities/Exchange
<input type="checkbox"/> 195 Contract Product Liability				<input type="checkbox"/> 875 Customer Challenge
<input type="checkbox"/> 196 Franchise				12 USC 3410
REAL PROPERTY	CIVIL RIGHTS	PRISONER PETITIONS	PROPERTY RIGHTS	
<input type="checkbox"/> 210 Land Condemnation	<input type="checkbox"/> 441 Voting	<input type="checkbox"/> 510 Motions to Vacate Sentence	<input type="checkbox"/> 861 HIA (1395f)	<input type="checkbox"/> 890 Other Statutory Actions
<input type="checkbox"/> 220 Foreclosure	<input type="checkbox"/> 442 Employment	<input type="checkbox"/> Habeas Corpus:	<input type="checkbox"/> 862 Black Lung (923)	<input type="checkbox"/> 891 Agricultural Acts
<input type="checkbox"/> 230 Rent Lease & Ejectment	<input type="checkbox"/> 443 Housing/ Accommodations	<input type="checkbox"/> 530 General	<input type="checkbox"/> 863 DIWC/DIWW (405(g))	<input type="checkbox"/> 892 Economic Stabilization Act
<input type="checkbox"/> 240 Torts to Land	<input type="checkbox"/> 444 Welfare	<input type="checkbox"/> 535 Death Penalty	<input type="checkbox"/> 864 SSID Title XVI	<input type="checkbox"/> 893 Environmental Matters
<input type="checkbox"/> 245 Tort Product Liability	<input type="checkbox"/> 445 Amer. w/Disabilities - Employment	<input type="checkbox"/> 540 Mandamus & Other	<input type="checkbox"/> 865 RSI (405(g))	<input type="checkbox"/> 894 Energy Allocation Act
<input type="checkbox"/> 290 All Other Real Property	<input type="checkbox"/> 446 Amer. w/Disabilities Other	<input type="checkbox"/> 550 Civil Rights		<input type="checkbox"/> 895 Freedom of Information Act
	<input type="checkbox"/> 440 Other Civil Rights	<input type="checkbox"/> 555 Prison Condition		<input type="checkbox"/> 900 Appeal of Fee Determination Under Equal Access to Justice
			FEDERAL TAX SUITS	<input type="checkbox"/> 950 Constitutionality of State Statutes
			<input type="checkbox"/> 870 Taxes (U.S. Plaintiff or Defendant)	
			<input type="checkbox"/> 871 IRS—Third Party	
			26 USC 7609	
			IMMIGRATION	
			<input type="checkbox"/> 462 Naturalization Application	
			<input type="checkbox"/> 463 Habeas Corpus – Alien Detainee	
			<input type="checkbox"/> 465 Other Immigration Actions	

## V. ORIGIN (Place an "X" in One Box Only)

- 1 Original Proceeding     2 Removed from State Court     3 Remanded from Appellate Court     4 Reinstated or Reopened     5 Transferred from another district (specify)     6 Multidistrict Litigation

Appeal to District

7 Judge from Magistrate Judgment

## VI. CAUSE OF ACTION

Cite the U.S. Civil Statute under which you are filing (Do not cite jurisdictional statutes unless diversity):

42 U.S.C. Section 9607 et seq.

Brief description of cause:

Environmental cost recovery action

## VII. REQUESTED IN COMPLAINT:

 CHECK IF THIS IS A CLASS ACTION    DEMAND \$ UNDER F.R.C.P. 23CHECK YES only if demanded in complaint:  
JURY DEMAND:  Yes  NoVIII. RELATED CASE(S)  
IF ANY

(See instructions):

JUDGE \_\_\_\_\_

DOCKET NUMBER \_\_\_\_\_

DATE

October 13, 2009    BRIAN M. LEDGER

SIGNATURE OF ATTORNEY OF RECORD

FOR OFFICE USE ONLY

RECEIPT # *6252*AMOUNT *350.00*

APPLYING IFFP

JUDGE

MAG. JUDGE

*MS 10/14/09*

**INSTRUCTIONS FOR ATTORNEYS COMPLETING CIVIL COVER SHEET FORM JS 44****Authority For Civil Cover Sheet**

The JS 44 civil cover sheet and the information contained herein neither replaces nor supplements the filings and service of pleading or other papers as required by law, except as provided by local rules of court. This form, approved by the Judicial Conference of the United States in September 1974, is required for the use of the Clerk of Court for the purpose of initiating the civil docket sheet. Consequently, a civil cover sheet is submitted to the Clerk of Court for each civil complaint filed. The attorney filing a case should complete the form as follows:

**I.** **(a) Plaintiffs-Defendants.** Enter names (last, first, middle initial) of plaintiff and defendant. If the plaintiff or defendant is a government agency, use only the full name or standard abbreviations. If the plaintiff or defendant is an official within a government agency, identify first the agency and then the official, giving both name and title.

**(b) County of Residence.** For each civil case filed, except U.S. plaintiff cases, enter the name of the county where the first listed plaintiff resides at the time of filing. In U.S. plaintiff cases, enter the name of the county in which the first listed defendant resides at the time of filing. (NOTE: In land condemnation cases, the county of residence of the "defendant" is the location of the tract of land involved.)

**(c) Attorneys.** Enter the firm name, address, telephone number, and attorney of record. If there are several attorneys, list them on an attachment, noting in this section "(see attachment)".

**II. Jurisdiction.** The basis of jurisdiction is set forth under Rule 8(a), F.R.C.P., which requires that jurisdictions be shown in pleadings. Place an "X" in one of the boxes. If there is more than one basis of jurisdiction, precedence is given in the order shown below.

United States plaintiff. (1) Jurisdiction based on 28 U.S.C. 1335 and 1338. Suits by agencies and officers of the United States are included here.

United States defendant. (2) When the plaintiff is suing the United States, its officers or agencies, place an "X" in this box.

Federal question. (3) This refers to suits under 28 U.S.C. 1331, where jurisdiction arises under the Constitution of the United States, an amendment to the Constitution, an act of Congress or a treaty of the United States. In cases where the U.S. is a party, the U.S. plaintiff or defendant code takes precedence, and box 1 or 2 should be marked.

Diversity of citizenship. (4) This refers to suits under 28 U.S.C. 1332, where parties are citizens of different states. When Box 4 is checked, the citizenship of the different parties must be checked. (See Section III below; federal question actions take precedence over diversity cases.)

**III. Residence (citizenship) of Principal Parties.** This section of the JS 44 is to be completed if diversity of citizenship was indicated above. Mark this section for each principal party.

**IV. Nature of Suit.** Place an "X" in the appropriate box. If the nature of suit cannot be determined, be sure the cause of action, in Section VI below, is sufficient to enable the deputy clerk or the statistical clerks in the Administrative Office to determine the nature of suit. If the cause fits more than one nature of suit, select the most definitive.

**V. Origin.** Place an "X" in one of the seven boxes.

Original Proceedings. (1) Cases which originate in the United States district courts.

Removed from State Court. (2) Proceedings initiated in state courts may be removed to the district courts under Title 28 U.S.C., Section 1441. When the petition for removal is granted, check this box.

Remanded from Appellate Court. (3) Check this box for cases remanded to the district court for further action. Use the date of remand as the filing date.

Reinstated or Reopened. (4) Check this box for cases reinstated or reopened in the district court. Use the reopening date as the filing date.

Transferred from Another District. (5) For cases transferred under Title 28 U.S.C. Section 1404(a). Do not use this for within district transfers or multidistrict litigation transfers.

Multidistrict Litigation. (6) Check this box when a multidistrict case is transferred into the district under authority of Title 28 U.S.C. Section 1407. When this box is checked, do not check (5) above.

Appeal to District Judge from Magistrate Judgment. (7) Check this box for an appeal from a magistrate judge's decision.

**VI. Cause of Action.** Report the civil statute directly related to the cause of action and give a brief description of the cause. **Do not cite jurisdictional statutes unless diversity.** Example: U.S. Civil Statute: 47 USC 553  
Brief Description: Unauthorized reception of cable service

**VII. Requested in Complaint.** Class Action. Place an "X" in this box if you are filing a class action under Rule 23, F.R.Cv.P.

Demand. In this space enter the dollar amount (in thousands of dollars) being demanded or indicate other demand such as a preliminary injunction.

Jury Demand. Check the appropriate box to indicate whether or not a jury is being demanded.

**VIII. Related Cases.** This section of the JS 44 is used to reference related pending cases if any. If there are related pending cases, insert the docket numbers and the corresponding judge names for such cases.

**Date and Attorney Signature.** Date and sign the civil cover sheet.

City of San Diego vs. National Steel & Shipbuilding Company, et al.

1                   **ATTACHMENT "A"**  
2                    **TO**  
3                   **CIVIL COVER SHEET**

4 NATIONAL STEEL & SHIPBUILDING CORPORATION; NATIONAL IRON  
5 WORKS; MARTINOLICH SHIP BUILDING COMPANY; SOUTHWEST MARINE,  
6 INC.; BAE SYSTEMS SAN DIEGO SHIP REPAIR, INC.; SAN DIEGO MARINE  
7 CONSTRUCTION COMPANY; STAR AND CRESCENT BOAT COMPANY, a  
8 division of SAN DIEGO MARINE CONSTRUCTION COMPANY; STAR AND  
9 CRESCENT BOAT COMPANY; STAR AND CRESCENT INVESTMENT  
COMPANY; STAR AND CRESCENT FERRY COMPANY; SAN DIEGO MARINE  
CONSTRUCTION CORPORATION; MCCSD; CAMPBELL INDUSTRIES; SAN  
DIEGO GAS & ELECTRIC; UNITED STATES NAVY; SAN DIEGO UNIFIED PORT  
DISTRICT; AND DOES 1-100, inclusive.

10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
  
COSD/1043756/7134737v1

Court Name: USDC California Southern  
Division: 3  
Receipt Number: CAS006252  
Cashier ID: msweeney  
Transaction Date: 10/14/2009  
Payer Name: SAN DIEGO LEGAL SUPPORT SVCS

---

CIVIL FILING FEE  
For: CITY OF SD V NATIONAL STEEL  
Case/Party: D-CAS-3-09-CV-002275-001  
Amount: \$350.00

---

CHECK  
Check/Money Order Num: 83231  
Amt Tendered: \$350.00

---

Total Due: \$350.00  
Total Tendered: \$350.00  
Change Amt: \$0.00

There will be a fee of \$45.00  
charged for any returned check.